

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

OIL CONS. DIV DIST. 3

SEP 30 2015

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

<b>Name of Company:</b> Energen Resources, Inc.	<b>Contact:</b> Ed Hasely
<b>Address:</b> 2010 Afton Place, Farmington, NM 87401	<b>Telephone No:</b> 505-324-4131
<b>Facility Name:</b> Jicarilla 94 #2B (API# -3003926856)	<b>Facility Type:</b> Oil and Gas Production Facility

<b>Surface Owner:</b> Jicarilla	<b>Mineral Owner:</b> Jicarilla	<b>Lease No.</b> Jicarilla
---------------------------------	---------------------------------	----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	27	27N	3W					Rio Arriba

Latitude 36.53884 Longitude -107.13400

**NATURE OF RELEASE**



<b>Type of Release:</b> None - Fire	<b>Volume of Release:</b> None - Fire	<b>Volume Recovered:</b> None - Fire
<b>Source of Release:</b> None - Fire	<b>Date and Hour of Occurrence:</b> 9/23/15 8:20 pm	<b>Date and Hour of Discovery:</b> 9/23/15 8:20 pm
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> Jonathan Kelly - OCD Bryce Hammond - Jicarilla Oil and Gas	
<b>By Whom?</b> Ed Hasely	<b>Date and Hour:</b> 9/24/15 at 8:00 am	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse.</b> NA	

**If a Watercourse was Impacted, Describe Fully.\*** NA

**Describe Cause of Problem and Remedial Action Taken.\*** It appears that lightening caused a fire on the vent (Enardo) valve on top of the oil storage tank on location. All that was burning was the vent gas out the Enardo valve. The fire was put out by the fire department with fire extinguishers.

**Describe Area Affected and Cleanup Action Taken.\*** There was no damage to the surrounding area. The Enardo valve will be replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Ed Hasely	Approved by District Supervisor: 	
Title: Sr. Environmental Engineer	Approval Date: 12/15/15	Expiration Date:
E-mail Address: ed.hasely@energen.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9/25/15 Phone: 505-324-4131 / 505-330-3584(cell)		

\* Attach Additional Sheets If Necessary

NSK 152 672 8987