

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Devon Energy	Contact Brett Fulks
Address 1751 Highway 511 P.O. 6459	Telephone No. 575-748-1844
Facility Name Nebu 460A	Facility Type CBM Well Location

Surface Owner BLM	Mineral Owner BLM	API No. 3004532279
----------------------	----------------------	-----------------------

LOCATION OF RELEASE

Unit Letter O	Section 07	Township 31N	Range 6w	Feet from the North/South Line 935'	Feet from the East/West Line 1340'	County San Juan
------------------	---------------	-----------------	-------------	---	--	--------------------

Latitude N36°54.6' Longitude W107°30.0'

OIL CONS. DIV DIST. 3
NOV 16 2015

NATURE OF RELEASE

Type of Release: Tank Fire- No Release-No Injuries- No EMS	Volume of Release No Release	Volume Recovered N/A
Source of Release: Lightning strike on produced water tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 10/26/2015 11:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Contacted OCD: Cory Smith, BLM Katherina Diemer	
By Whom? Jake Nossaman - Assistant Forman	Date and Hour 10/27/2015 3:47PM	Email- 5 PM
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A



Describe Cause of Problem and Remedial Action Taken.*

Lightning struck a 56" produced water tank on the NEBU 460A. The strike caused a fire on the tank and then extinguished on its own. No release occurred and no injuries occurred. In addition, no emergency services were called or needed. Actions taken: Incident reporting and investigation.

Describe Area Affected and Cleanup Action Taken.*

56" 100 bbl produced water tank.- No Release-

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Brett Fulks	Approved by Environmental Specialist: 	
Title: EHS Professional	Approval Date: 12/23/2015	Expiration Date:
E-mail Address: Brett.Fulks@dmn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/30/2015	Phone: 575-748-1844	

* Attach Additional Sheets If Necessary

NUF 153575230

①