

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

OIL CONSD. DIV DIST. 3

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JAN 13 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: XTO Energy, Inc.	Contact: Rex Farnsworth
Address: 382 Road 3100, Aztec, New Mexico 87410	Telephone No.: (505) 333-3100
Facility Name: Federal Gas Com 1 #1C	Facility Type: Gas Well (Blanco Mesaverde)

Surface Owner: Federal	Mineral Owner	API No.: 30-045-30144
------------------------	---------------	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	20	32N	10W	1060	FNL	660	FWL	San Juan

Latitude 36.976050 Longitude -108.124597

NATURE OF RELEASE


Type of Release: Produced Oil / Produced Water	Volume of Release: 180 BBL's	Volume Recovered: 70 BBL's
Source of Release: Production Tank	Date and Hour of Occurrence: 12/30/2015 Time: Unknown	Date and Hour of Discovery: 12-30-2015 12:25pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith (NMOCD)	
By Whom? James McDaniel (EHS Supervisor XTO Energy)	Date and Hour: 12-30-2015 4:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* On Wednesday, 12-30-2015 an XTO Foreman found the steel production tank on the Federal Gas Com 1#1C location leaking from the load line valve. The XTO Foreman determined by the ending gauge of the tank that approximately 180 barrels of total fluid, 20 barrels of produced water and 160 barrels of produced oil has been released. The spill was contained within the berm and never left location. The XTO Foreman then called Triple S Trucking to help aid with product recovery and notified EH&S. The Foreman was able to recover approximately 70 barrels of produced fluid. The site was then ranked according to the NMOCD Guidelines for the Remediation of Leaks, Spills and Releases. The site was ranked a 20 due to an estimated depth to groundwater of 50 to 100 feet and an arroyo less than 1000 feet. This set the closure standard to 100 ppm TPH, 10 ppm benzene, and 50 ppm total BTEX.

Describe Area Affected and Cleanup Action Taken.* A release has been confirmed based a broken load line valve on the production tank and the loss of 110 barrels of fluid that was not recovered. Clean-up is still ongoing.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Initial Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Rex Farnsworth	Approved by Environmental Specialist: 	
Title: EHS Technician	Approval Date: 1/22/2016	Expiration Date:
E-mail Address: rex_farnsworth@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1-8-2016 Phone: 505-333-3100		

* Attach Additional Sheets If Necessary

NCS1536539728

①