

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED  
OMB No. 1004-0137  
Expires: October 31, 2014

**SUNDRY NOTICES AND REPORTS ON WELLS**

**Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.**

5. Lease Serial No.  
NMSF - 078931D (WC)

6. If Indian, Allottee or Tribe Name

**SUBMIT IN TRIPLICATE - Other instructions on page 2.**

1. Type of Well  
 Oil Well  Gas Well  Other

7. If Unit of CA/Agreement, Name and/or No.

2. Name of Operator  
GREAT WESTERN DRILLING COMPANY

8. Well Name and No.  
CALLOW FEDERAL 1G

3a. Address  
P.O. BOX 1659 MIDLAND, TX 79702

3b. Phone No. (include area code)  
(432)682-5241

9. API Well No.  
30-045-32164

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
835 SOUTH 1915 EAST  
UL: , Sec: 33, T: 29N, R: 13W

10. Field and Pool or Exploratory Area  
BASIN DAKOTA (PRORATED GAS)

11. County or Parish, State  
SAN JUAN NM

**12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other <u>Repair Pipeline &amp; return to production</u>
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

This well has been shut in and non-productive since July 2014 due to a defective flowline. Great Western proposes to replace a small section of the flowline (30' - 60'), then return this well to production as soon as BLM approvals are received.

OIL CONS. DIV DIST. 3

FEB 19 2016

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

CARY BILLINGSLEY

Title AREA ENGINEER

Signature

*Cary N. Billingsley*

Date 01/12/2016

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

*Jack Sawyer*

Title

PE

Date

2/17/16

Office

FFO

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

61 NMOCD Accepted For Record  
Ar