

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

APR 27 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: BP	Contact: Steve Moskal
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 505-326-9497
Facility Name: Heaton Com LS 009	Facility Type: Natural gas well

Surface Owner: Federal	Mineral Owner: Federal	API No. 3004510170
------------------------	------------------------	--------------------

LOCATION OF RELEASE

Unit Letter B	Section 32	Township 31N	Range 11W	Feet from the 990	North/South Line South	Feet from the 1,495	East/West Line East	County: San Juan
------------------	---------------	-----------------	--------------	----------------------	---------------------------	------------------------	------------------------	------------------

Latitude 36.86006° Longitude -108.01025°

NATURE OF RELEASE

Type of Release: natural gas	Volume of Release: 316 mcf	Volume Recovered: none
Source of Release: Water dump valve.	Date and Hour of Occurrence: 4/7/2016 @ 11:30 PM	Date and Hour of Discovery: 4/14/2016 @ 11:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* BP representative found water dump from separator hung open with gas venting out into the production pit. The well was shut in until pressure was equalized. The water dump controller was adjusted.

Describe Area Affected and Cleanup Action Taken.* Hung dump valve vented directly to below grade tank and atmosphere. No action necessary outside of repair/adjustment of dump valve.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Steve Moskal	Approved by Environmental Specialist: 	
Title: Field Environmental Coordinator	Approval Date: <u>4/27/2016</u>	Expiration Date:
E-mail Address: steven.moskal@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: April 20, 2016	Phone: 505-326-9497	

* Attach Additional Sheets If Necessary

NUF1611829098

①