

RECEIVED

MAR 22 2016

Form 3160-5
(August 2007)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

Farmington Field Office
Bureau of Land Management

SUBMIT IN TRIPLICATE - Other Instructions on page 2.

1. Type of Well
 Oil Well Gas Well Other

2. Name of Operator
Black Hills Gas Resources, Inc.

3a. Address
3200 N 1st St, Bloomfield, NM 87413

3b. Phone No. (include area code)
(505) 634-5104

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
2050' FNL & 630' FEL SE/SE Section 11 T29N R3W (UL:H)

5. Lease Serial No.
MDA 701-98-0013, Tract 2

6. If Indian, Allottee, or Tribe Name
Jicarilla Apache Tribe

7. If Unit or CA. Agreement Name and/or No.

8. Well Name and No.
Jicarilla 29-03-11 #2

9. API Well No.
30-039-26731

10. Field and Pool, or Exploratory Area
Cabresto Canyon Tertiary

11. County or Parish, State
Rio Arriba County, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/ Resume)	<input type="checkbox"/> Water Shut-off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug back	<input type="checkbox"/> Water Disposal	

*13. Describe Proposed or Completed Operation Clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

Black Hills Gas Resources intends to plug and abandon Jicarilla 29-03-11 #2 and will submit the procedure within the next 90 days.

ACCEPTED FOR RECORD

APR 19 2016

FARMINGTON FIELD OFFICE
BY: *[Signature]*

OIL CONS. DIV DIST. 3

APR 20 2016

14. I hereby certify that the foregoing is true and correct. Name (Printed/ Typed)

Daniel Manus Title **Regulatory Techician II**

Signature *[Signature]* Date **March 22, 2016**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by _____ Title _____ Date _____

Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office _____

Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOCD Accepted For Record