#### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPRO	VED
OMB NO. 1004-	013:
Expires: July 31,	2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.

5. Lease Serial No. NMSF078209B

	ell. Use form 3160-3 (APD) f	or such proposals.	6. If Indian, Allottee	e or Tribe Name	
SUBMIT IN TR	IPLICATE - Other instruction	ns on reverse side.	7. If Unit or CA/Ag	reement, Name and/or No.	
1. Type of Well			8. Well Name and N	lo. NYON UNIT 569	
Oil Well Gas Well O  2. Name of Operator	ther Contact: TO	YA COLVIN	9. API Well No.		
BP AMERICA PRODUCTION	N CO E-Mail: Toya.Colvin@l		30-045-30330		
3a. Address 200 ENERGY COURT FARMINGTON, NM 87401		o. Phone No. (include area code h: 281.366.7148	10. Field and Pool,	Field and Pool, or Exploratory     BASIN FRUITLAND COAL	
4. Location of Well (Footage, Sec.,	T., R., M., or Survey Description)		11. County or Parisi	h, and State	
Sec 33 T29N R12W SWNE 1	1855FNL 1680FEL		SAN JUAN CO	OUNTY, NM	
12. CHECK APP	PROPRIATE BOX(ES) TO IN	NDICATE NATURE OF	NOTICE, REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION		TYPE O	F ACTION		
Notice of Intent	Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
Notice of Intent     ■	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug and Abandon	□ Temporarily Abandon		
Bol	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal		
	ect well. A procedure including the BLM Pit Rule 19.15.17.9 NMAC, BF PEPTANCE OF THIS NOTE THE LESSEE AND SING ANY OTHER RED FOR OPERATIONS	outly NMOCD 24 hrs	euments.	NS. DIV DIST. 3	
14. I hereby certify that the foregoing is  Co  Name (Printed/Typed) TOYA CO	Electronic Submission #3489 For BP AMERICA PR ommitted to AFMSS for process	RODUCTION CO, sent to the sing by JACK SAVAGE on (	e Farmington		
10					
Signature (Electronic	Submission)	Date 08/24/2	016		
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE USE		
Approved By JACK SAVAGE		TitlePETPOLE	IIM ENGINEED		
		_ I I I I I I I I I I I I I I I I I I I	UM ENGINEER	Date 08/26/2016	

June 3<sup>rd</sup> 2016 NMOCD

BP would like to permanently plug and abandon well **Gallegos Canyon Unit #569** as per the attached procedure and wellbore schematics.

#### PLUG AND ABANDONMENT PROCEDURE

	Basin Fruitland Coal			
	2180' FNL and 790' FEL, Section 33, T29N, R12W			
	San Juan County, New Mexico / API 30-045-30330			
	Lat: N/ Lat: W			
Note:	All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.			
1.	Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.			
2.	Rods: Yes_X_, No, Unknown			
	Tubing: Yes X, No , Unknown , Size 2.375", Length 1310'.			
	Packer: Yes, No _X, Unknown, Type			
	If this well has rods or a packer, then modify the work sequence in step #2 as appropriate. Round trip 4.5" mill to 1127'.			
3.	Plug #1 (Fruitland Coal interval, Pictured Cliffs and Fruitland top, 1127' – 910'): RIH and set 4.5" CR at 1127'. Circulate well clean. Pressure test tubing to 1000#. Pressure test casing to			

- 4.5" CR at 1127'. Circulate well clean. Pressure test tubing to 1000#. Pressure test casing to 800#. <u>If casing does not test then spot or tag subsequent plugs as appropriate.</u> Mix 21 sxs Class B cement inside casing from 1127' to isolate the Fruitland Coal interval and cover the Pictured Cliffs and Fruitland tops. PUH.
- 4. Plug #2 (Kirtland top and 7" casing shoe, 210' 0'): Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 20 sxs cement and spot a balanced plug from 210' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the casing and annulus from the squeeze holes to surface. Shut in well and WOC.
- ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A
  marker to comply with regulations. Record GPS coordinate for P&A marker on tower report.
  Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM
  stipulations

# Gallegos Canyon Unit #569

## Proposed P&A

**Basin Fruitland Coal** 2180' FNL, 790' FEL, Section 33, T-29-N, R-12-W San Juan County, NM, API #30-045-30330

Today's Date: 4/1/16 Spud: 9/15/00

Completed: 11/21/2000 Elevation: 5396' GI


8.75" hole

Kirtland @ 160'

Fruitland @ 960'

Pictured Cliffs @ 1120'

6-1/4" hole



TOC @ surface

7" 20# J-55 Casing set @ 135' Cement with 100 sxs, circulated

> Plug #2: 210' - 0' Class B Cement, 20 sxs

> Plug #1: 1127' - 910' Class B Cement, 21 sxs

Set CR @ 1127'

Fruitland Coal Perforations: 1177' - 1314'

4.5",10.5#, J-55 Casing set @ 1474' Cement with 191 sxs Class H, Circulate good cement to pit.

#### CORRPRO - PLUG AND ABANDON - DEEP ANODE GROUND BED

Permits: Corrpro will assist the Company in applications for permits required by any City, County and/or State agencies.

Anode Hole/Surface Casing: At the surface of the anode bed the surface casing shall be excavated or hydro-excavated at a depth of 3' below grade. All conduits and wires shall be terminated and removed. The surface casing and vent pipe will be cut down flush at 2' below grade. Anode leads, after terminated, will be left in the well bore. If the anode bore is open, a bentonite and water mixture will be poured in to backfill. A cement mixture of Portland cement shall be poured as backfill around the anode bed bore to approximately 6" above remaining surface casing. The excavation shall then be backfilled with native soil.

#### ANODE LEAD JUNCTION BOX

Removal: The anode lead junction box immediately adjacent to the deep anode will be removed along with all remaining conduits and wiring. The 4x4 post will be removed along with the concrete pad and backfilled to grade with native soil.

#### **NEGATIVE/POSITIVE CABLES**

Termination of negative/positive leads will be left to the discretion of the owner.

CO. - FARMINGTON, HM (ANODE BED FILL)\340140538-01.dwg LAYOUT: Model DDDDB 300 100 280 BACKFILLED TO GRADE LEVEL WITH NATIVE SOIL -65' BENTONITE/WATER BACKFILL -215' (CEMENT BACKFILLED BOTTOM LOADED THRU DRILL STEM) (5 GALLONS OF WATER TO EVERY 5 BAGS OF BENTONITE) ANODE LEADS TERMINATED 8"
(SCH 40) CASING An Aegion Company 18" TO 24" CATHODIC WELL 340140538 340140538-01

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon: Re: Permanent Abandonment Well: Gallegos Canyon Unit #569

### CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
  - a) Set Plug #2 (232-0) ft. to cover the Kirtland top. BLM picks top of Kirtland at 182 ft.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.