



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop
Cabinet Secretary

Lori Wrotenbery
Director

Oil Conservation Division

June 25, 2003

Gary Brink
Energen Resources
2198 Blmfld Hwy
Farmington NM 87410

RE: Incomplete Bradenhead test reports.

Dear Mr. Brink:

The Bradenhead test on the following list of wells does not provide the information required for a complete test. Please review the bradenhead testing procedures, retest the wells and submit a complete test form before July 15, 2003.

30-045-07360
Hancock 8, the submitted test form has no pressures on it at all.

30-045-05874 ~~DE NA HAZZA 1~~, the submitted test form does not indicate a bradenhead pressure.

30-45-11676 ~~TIBBAR FEDERAL 1~~, the submitted test form does not indicate a bradenhead pressure.

30-045-29141 ~~TIBBAR FEDERAL 1E~~, the submitted test form does not indicate a bradenhead pressure.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Charlie T. Perrin
Deputy Oil & Gas Inspector
cperrin@state.nm.us

CTP/mk

CC: CTP
Well File