| to Appropriate District Office   | ALUTANCE A A V   |
|--|--|
| DISTRICT I<br>P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION<br>P.O. Box 2088  | WELL API NO.<br>36-031-20832   |
| DISTRICT II P.O. Drawer DD. Artesia, NM 88210  Santa Fe, New Mexico 87504-2088   | 5. Indicate Type of Lease  |
| DISTRICT III   | STATE FEE  |
| 1000 Rio Brazos Rd., Aztec, NM 87410   | 6. State Oil & Gas Lease No.   |
| SUNDRY NOTICES AND REPORTS ON WELLS  ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)   | 7. Lease Name or Unit Agreement Name   |
| 1. Type of Well: Oil. OAS  | Hospat Sand Unit   |
| WEIL WEIL OTHER WILL   | 8. Well No.  |
| 2. Name of Operator BCED OPERATING, INC.   | 9. Pool pame or Wildcat  |
| 3. Address of Operator P.O. BCX 1680, Hebbs, pm 88241  | HOSPAH WARER SAND  |
| 4. Well Location Z 600 EAST 20   | D Feet From The SOUTH Line   |
|  | ,  |
| Section Township /8 Range 9 (A)  | NIMPM Trokinley County   |
| XIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII   |  |
| 11. Check Appropriate Box to Indicate Nature of Notice, I  |  |
| NOTICE OF INTENTION TO:  | BSEQUENT REPORT OF:  |
| PLUG AND ABANDON REMEDIAL WORK   | ALTERING CASING  |
| PERFORM REMEDIAL WORK PLUG AND ABANDON PREMEDIAL WORK  |  |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN  | IG OPNS. PLUG AND ABANDONMENT  |
| PENFORM REMEDIAL WORK  |  |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN  |  |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN  PULL OR ALTER CASING CASING CASING TEST AND COMMENCE DRILLIN  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incl  work) SEE RULE 1103.  | EMENT JOB  |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN  PULL OR ALTER CASING CASING CASING TEST AND COMMENCE DRILLIN  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incl  | SEMENT JOB   |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN  PULL OR ALTER CASING CASING TEST AND COMMENCE DRILLIN  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incl  work) SEE RULE 1103.  PLEASE SEE ATTACh mynts.   | EMENT JOB  |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN PULL OR ALTER CASING CASING TEST AND CONTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incl. work) SEE RULE 1103.  PLEASE SEE ATTACh mynts.  | Tuding estimated date of starting any proposed   |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN  PULL OR ALTER CASING CASING TEST AND CONTRER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incl.  work) SEE RULE 1103.  PLEASE SEE ATTACh mysts.  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  | Leding estimated date of starting any proposed  The Old Color Starting and Starting any proposed  The Old Color Starting and  |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN PULL OR ALTER CASING CASING TEST AND CONTRER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incl work) SEE RULE 1103.  PLEASE SEE ATTRICAMY YATS.  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE  TITLE  Resident   | Tuding estimated date of starting any proposed   |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN PULL OR ALTER CASING CASING TEST AND COMMENCE DRILLIN CASING TEST AND COMMENCE DRI | DATE SUS-397-3972 TELEPHONE NO.  |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN PULL OR ALTER CASING CASING TEST AND COMMENCE DRILLIN CASING TEST AND COMMENCE DRI | Letter Job Date  D |

CONDITIONS OF APPROVAL, IF ANY:

# HOSPAH SAND UNIT # 101

30-031-20832 SEC. 36,T18N,R9W MCKINLEY, NM

12 1/4" HOLE @ 41'

8 5/8" 23# SURFACE CASING @ 41' CMT. CIRCULATED

7 7/8" HOLE @ 41'- 1768'

5 1/2" 14# CASING @ 1767' CMTD W/ 100 SXS

PERFS @ 1729'- 1750'

TOPS: MENEFEE

@ SURFACE POINT LOOKOUT 530'

@

GALLUP @ 1560'

# HOSPAH SAND UNIT # 101 30-031-20832 SEC. 36,T18N,R9W MCKINLEY, NM

#### PROPOSED P & A PROCEDURE

- \*\* PREPARE LOCATION
- \*\* MIRU PLUGGING EQUIPMENT, RLS PKR AND POOH W\TBG, PU AND TIH WITH 2 7/8" TBG. TO 1750', LOAD CASING WATER AND CIRCULATE HOLE CLEAN, MIX AND PUMP 45 SXS. CLASS "B" CMT. AND SPOT BALANCED PLUG AT 1360'-1750', POH WITH TBG., SECURE WELL, WOC OVERNIGHT
- \*\* CREW TO LOCATION, CONDUCT SAFETY MEETING, RIG UP WIRELINE TRUCK, TAG TOC AT 1360' (1460' MIN), IF TOC MEETS NMOCD REQUIREMENTS PROCEED TO PROCEDURE "A" IF THE TOC DOES NOT MEET NMOCD REQUIREMENTS PROCEED TO PROCEDURE "B"

### PROCEDURE "A"

- \*\* CUT CASING AT 580', RIG DOWN WIRELINE TRUCK
- \*\* POOH, LAY DOWN CASING
- \*\* TIH W/ TBG, ROTATE INTO CASING STUB @ 580', CONTINUE IN HOLE TO 630' (50' INSIDE STUB), BREAK CIRCULATION, CIRCULATE HOLE CLEAN, MIX AND PUMP 92 SXS CLASS "B" CMT, SPOT BALANCED PLUG @ 330' TO 630', (100% EXCESS IN OPEN HOLE), POOH W/ TBG, SECURE WELL, SDFN, WOC
- \*\* TIH W/TBG. TAG TOC @ 330' (430' MIN), POOH W/ TBG TO 91', BREAK CIRCULATION, CIRCULATE HOLE CLEAN, MIX AND PUMP 41 SXS CLASS "B" CMT, CIRCULATE SLURRY TO PIT, POOH W/TBG,

- \*\* RIG DOWN PLUGGING EQUIPMENT, ASCERTAIN HOLE TO BE STABLE, TOP OFF CASING IF NECESSARY, INSTALL P&A MARKER, RIG DOWN AND MOVE ALL EQUIPMENT
- \*\* RESTORE LOCATION

# PROCEDURE "B"

- \*\* MIX AND PUMP SUFFICIENT CEMENT TO ESTABLISH A SATISFACTORY TOC, CEMENT WILL BE PUMPED THROUGH TBG AND A BALANCED PLUG WILL BE ACHIEVED, POH WITH TBG WOC
- \*\* TIH WITH TBG, TAG TOC AND THEN PROCEED TO PROCEDURE "A"