Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

NMSF078278

SUNDRY NOTICES	AND REPORTS	ON WELLS
----------------	-------------	----------

ield Office 6. If Indian, Allottee or Tribe Name

	e this form for proposals well. Use Form 3160-3 (
SL	JBMIT IN TRIPLICATE - Other in	structions on page 2.	7. If Unit of CA/Agreement, N	lame and/or No.
1. Type of Well Oil Well	X Gas Well Other	8. Well Name and No. San Jua	an 29-6 Unit 33F	
2. Name of Operator	Hilcorp Energy Comp	pany	9. API Well No. 30-0	039-27552
3a. Address 382 Road 3100, Aztec, N	NM 87410	3b. Phone No. (include area co	,	ory Area C/Blanco MV/Basin DK
4. Location of Well (Footage, Sec., T.,R Surface Unit G (S'	R.,M., or Survey Description) WNE) 2385'FNL & 1255'	FEL, Sec. 13, T29N, R06	11. Country or Parish, State Rio Arriba	, New Mexico
12. CHECK 1	THE APPROPRIATE BOX(ES	S) TO INDICATE NATURE	OF NOTICE, REPORT OR OTH	ER DATA
TYPE OF SUBMISSION		TYPE	OF ACTION	
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat	Reclamation	Well Integrity
Subsequent Report 00	Casing Repair	New Construction	X Recomplete	Other
Subsequent Report	Change Plans	Plug and Abandon	Temporarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	
			date of any proposed work and approxing red and true vertical depths of all pertine	

following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

*** Revised procedure - updated PC perforations ***

Hilcorp Energy Company plans to recomplete the subject well in the Pictured Cliffs formation and downhole commingle with the existing Mesaverde and Dakota. Attached is the PC C102, recomplete procedure & wellbore schematic. The DHC application will be submitted and approved prior to commingling. A Closed Loop system will be utilized.

HOLD CHOAFOR DHC

SEE ATTACHED

FOR CONDITIONS

OF APPROVAL

NMOCD

JUN 2 2 2018

DISTRICT 111

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND **OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS** ON FEDERAL AND INDIAN LANDS

Notify NMOCD 24 hrs

pr	ior to beg				
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)	T				
Tammy Jones	Title	Operations/Regulatory	Technician - Sr.		
Signature Tammy Jusy	Date	6/19/2018			
THIS SPACE FOR FEI	DERAL C	R STATE OFFICE USE			
Approved by William Tambekon		Title Letroleum	Engineer	Date	6/20/2018
Conditions of approval, if any, are attached. Approval of this notice does not warrant of that the applicant holds legal or equitable title to those rights in the subject lease which	-	Office FF0			/ /
	-	Office FFO	0		, ,

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone: (505) 334-6178 Fax: (505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505

Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico **Energy, Minerals and Natural** Resources **Oil Conservation Division** 1220 S. St Francis Dr.

Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 252383

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number	2. Pool Code	3. Pool Name
30-039-27552	77440	GOBERNADOR PICTURED CLIFFS (GAS)
4. Property Code	5. Property Name	6. Well No.
318838	SAN JUAN 29 6 UNIT	033F
7. OGRID No.	8. Operator Name	9. Elevation
372171	HILCORP ENERGY COMPANY	6756

10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
G	13	29N	06W		2385	N	1255	Е	RIO ARRIBA

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated A	Acres 2.16 E/2		13. Joint or Infill		14. Consolidation	n Code		15. Order No.	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION


OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division. E-Signed By: Tammy Jones Title: Operations/Regulatory Technician - Sr. Date: 5/17/2018
Title: Operations/Regulatory Technician - Sr.
Surveyed By: Jason C. Edwards
Date of Survey: 7/1/2004
Certificate Number: 15269



JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2 3/8" tubing set at 8,042'.
- 3. Set a 4-1/2" cast iron bridge plug at +/- 3,900' to isolate the Mesa Verde and Dakota Formations. (Note: TOC at 3,090' by CBL.)
- 4. Load the hole and pressure test the casing to frac pressure.
- 5. N/D BOP, N/U frac stack and test frac stack to frac pressure.
- 6. Perforate and frac the Pictured Cliffs in a single stage (Top Perforation @ 3,683"; Bottom Perforation @ 3,763").
- 7. Isolate frac stage with a composite bridge plug.
- 8. Nipple down frac stack, nipple up BOP and test.
- 9. TIH with a mill and drill out top Pictured Cliffs isolation plug.
- 10. Clean out to Mesa Verde and Dakota isolation plug and, when water and sand rates are acceptable, flow test the Pictured Cliffs.
- 11. Drill out Mesa Verde and Dakota isolation plug and cleanout to PBTD of 8,175'. TOOH.
- 12. TIH and land production tubing. Get a tri-mingled Mesa Verde + Dakota + Pictured Cliffs flow rate.







United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Farmington District Office 6251 College Blvd. - Suite A Farmington, New Mexico 87402 www.blm.gov/nm



CASING REPAIR, WORKOVER, AND RECOMPLETION CONDITION OF APPROVAL

- 1. If casing repair operations are needed, obtain prior approval from this office before commencing repairs.
- 2. If a CBL or other logs are run, provide this office with a copy.
- 3. After any casing repair operations, test cement squeeze to a minimum of 500# for 30 minutes with no more than 10 % pressure fall off in the 30 minutes test period. Provide test chart with your subsequent report of operations
- 4. A properly functioning BOP and related equipment must be installed prior to commencing workover, casing repair, and/or recompletion operations.
- 5. Contact this office at (505) 564-7750 prior to conducting any cementing operations

SPECIAL STIPULATIONS:

- 1. Pits will be fenced during work-over operation.
- 2. All disturbance will be kept on existing pad.
- 3. All pits will be pulled and closed immediately upon completion of the recompletion and work-over activities.
- 4. Pits will be lined with an impervious material at least 12 mils thick.

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

MAY 17 2013

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010

Lease Serial No. Farmington Field Office NMSF078278 SUNDRY NOTICES AND REPORTS ON WELLS Bureau of d. HTmdian Allotter or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well Oil Well X Gas Well Other 8. Well Name and No. San Juan 29-6 Unit 33F 9. API Well No. 2. Name of Operator 30-039-27552 **Hilcorp Energy Company** 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 382 Road 3100, Aztec, NM 87410 505-599-3400 Gobernador PC/Blanco MV/Basin DK 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State Unit G (SWNE) 2385'FNL & 1255' FEL, Sec. 13, T29N, R06W Rio Arriba New Mexico 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION X Notice of Intent Production (Start/Resume) Water Shut-Off Acidize Deepen Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction X Recomplete Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Hilcorp Energy Company plans to recomplete the subject well in the Pictured Cliffs formation and downhole commingle with the existing Mesaverde and Dakota. Attached is the PC C102, recomplete procedure & wellbore schematic. The DHC application will be submitted and approved prior to commingling. A Closed Loop system will be utilized. BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND MAY 3 D 2018 OPERATOR FROM OBTAINING ANY OTHER SEE ATTACHED **AUTHORIZATION REQUIRED FOR OPERATIONS** FOR CONDITIONS ON FEDERAL AND INDIAN LANDS OF APPROVAL 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) **Tammy Jones** Operations/Regulatory Technician - Sr. Signature Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

entitle the applicant to conduct operations thereon

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would

Approved by

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico **Energy, Minerals and Natural** Resources

Oil Conservation Division 1220 S. St Francis Dr.

Santa Fe, NM 87505

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-039-27552	2. Pool Code 77440	3. Pool Name GOBERNADOR PICTURED CLIFFS (GAS)
4. Property Code 318838	5. Property Name SAN JUAN 29 6 UNIT	6. Well No. 033F
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 6756

10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
G	13	29N	06W		2385	N	1255	E	RIO ARRIBA

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated A			13. Joint or Infill		14. Consolidatio	n Code		15. Order No.	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

OPERATOR CERTIFICATION

Form C-102

August 1, 2011

Permit 252383

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By:

Tammy Jones

Title:

Operations/Regulatory Technician - Sr.

Date:

5/17/2018

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

Jason C. Edwards

Date of Survey:

7/1/2004

Certificate Number:


15269



JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2 3/8" tubing set at 8,042'.
- 3. Set a 4-1/2" cast iron bridge plug at +/- 3,900' to isolate the Mesa Verde and Dakota Formations. (Note: TOC at 3,090' by CBL.)
- 4. Load the hole and pressure test the casing to frac pressure.
- 5. N/D BOP, N/U frac stack and test frac stack to frac pressure.
- 6. Perforate and frac the Pictured Cliffs in a single stage (Top Perforation @ 3,603'; Bottom Perforation @ 3,794').
- 7. Isolate frac stage with a composite bridge plug.
- 8. Nipple down frac stack, nipple up BOP and test.
- 9. TIH with a mill and drill out top Pictured Cliffs isolation plug.
- 10. Clean out to Mesa Verde and Dakota isolation plug and, when water and sand rates are acceptable, flow test the Pictured Cliffs.
- 11. Drill out Mesa Verde and Dakota isolation plug and cleanout to PBTD of 8,175'. TOOH.
- 12. TIH and land production tubing. Get a tri-mingled Mesa Verde + Dakota + Pictured Cliffs flow rate.







United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Farmington District Office 6251 College Blvd. - Suite A Farmington, New Mexico 87402 www.blm.gov/nm



CASING REPAIR, WORKOVER, AND RECOMPLETION CONDITION OF APPROVAL

- 1. If casing repair operations are needed, obtain prior approval from this office before commencing repairs.
- 2. If a CBL or other logs are run, provide this office with a copy.
- 3. After any casing repair operations, test cement squeeze to a minimum of 500# for 30 minutes with no more than 10 % pressure fall off in the 30 minutes test period. Provide test chart with your subsequent report of operations
- 4. A properly functioning BOP and related equipment must be installed prior to commencing workover, casing repair, and/or recompletion operations.
- 5. Contact this office at (505) 564-7750 prior to conducting any cementing operations

SPECIAL STIPULATIONS:

- 1. Pits will be fenced during work-over operation.
- 2. All disturbance will be kept on existing pad.
- 3. All pits will be pulled and closed immediately upon completion of the recompletion and work-over activities.
- 4. Pits will be lined with an impervious material at least 12 mils thick.