District Office			
DISTRICT		ATION DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240		ox 2088/	30-031-20003
DISTRICT II	Santa Fe, New Me	exico 87504-2088	5 Indicate Time of Lases
P.O. Drawer DD, Artesia, NM 88210		Ë	STATE FEE
DISTRICT III			6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410			O' STATE OIL SE GES TYPES TANK
SUNDRY NOT	ICES AND REPORTS OF	N WELLS	
(DO NOT USE THIS FORM FOR PR	OPOSALS TO DRILL OR TO D	EEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESE	RVOIR. USE "APPLICATION F 2-101) FOR SUCH PROPOSALS	OH PEHMII S1	
	-101) FOR SOCH PHOP COALS	<u>.,, </u>	-
1. Type of Well:			La TE POULD I
WEIT WEIT	(OTHER)	WIW	2917G FE RailRoad
2. Name of Operator		•	8. Well No.
BCED OPERA	Ting, Inc.		I D. D. L
1.3. Address of Operator			9. Pool name or Wildcat
1 7.0. Box 168	, Hebbs, nm	88241	HUSPAH UPPER Sand
T 4 997 00 7			- /
Unit Letter $B : 33$	O Feet From The NOR	1H Line and d	310 Feet From The <u>East</u> Line
One Date:	, ***		<i>)</i> ,
Section 07	Township TIIN	Range $\mathcal{S}\mathcal{W}$	NIMPM MCANCEY County
	10. Elevation (Show	Range & W whether DF, RKB, RT, GR, etc.)	
		6904'	<u> </u>
Chaok	Appropriate Box to Inc	licate Nature of Notice,	Report, or Other Data
		l CII	BSEQUENT REPORT OF:
NOTICE OF IN	TENTION TO:	J 30	DSEQUEIVI FILL OIT OIT.
	DI LIO AND ADANDON	REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON	E NEMEDIAL WORK	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI	NG OPNS. L. PLUG AND ABANDONMENT L.
PULL OR ALTER CASING		CASING TEST AND	CEMENT JOB L.
		OTHER:	
OTHER:			
12. Describe Proposed or Completed Ope	rations (Clearly state all pertinent	details, and give pertinent dates, inc	luding estimated date of starting any proposed
work) SEE RULE 1103.			
·			
P/6000	EE ATTACKA	-Le	
120438 3		シャクフユ	A STATE OF THE STA
• •	ZE MITACHI	ne11-,	CONTRACTOR OF THE PARTY OF THE
•	ZE MITACIII	meni	
•	ee minacin	meni	Maria
•	ee princin	menta.	O May 300
	ee princin	nent	Of May 300 33
	ee 19174 C117	nent	OL MAY DO
	ee princin	nent	OL MAY DOO SEED
	ee princin	nent-,	OL MAY DOO STORY
	ee 19174 (1117	nent-	a May too of the state of the s
	ee princin	menta.	Q. May 300 337
	ee 19114011	menta.	a May Day Sign of Sign
	ee 19114011	menta.	OF TEST
		A CHILLIPSON	OL MAN OR SERVICE OF THE SERVICE OF
I hereby certify that the information above is		owledge and belief.	St E 7 2 2
1 loopie		A CHILLIPSON	OL 100 300 300 300 300 300 300 300 300 300
I hereby certify that the information above is SIGNATURE		owledge and belief.	505-397-3972
1 loopie		owledge and belief.	505 -397 - 397 2
SIGNATURE ACCOUNTS		owledge and belief. TITLE RESIDE	505-397-3972_ TELEPHONE NO.
SIGNATURE ACCOUNTS		owledge and belief. TITLE RESIDE	505-397-3972_ TELEPHONE NO.
SIGNATURE ADONAL TYPE OR PRINT NAME DO NOTAL		owledge and belief. TITLE RESIDE	505-397-3972_ TELEPHONE NO.
TYPE OR PRINT NAME DO NO (This space for State Use)		owledge and belief. TITLE RESIDE	505 -397 - 397 2
SIGNATURE DO NO IN		OVERUTY GIL & GA	505-397-3972_ TELEPHONE NO.

SANTA FE RAILROAD # 10

30-031-20003 SEC. 07, T17N, R8W MCKINLEY, NM

8 5/8" 24# SURFACE CASING @ 23' CMT. CIRCULATED

7 7/8" HOLE 23'- 1595'

5 1/2" 14.0# CASING @ 1595' CMTD W/ 100 SXS

PBTD @ 1583'

PERFS @ 1541'- 1569'

TOPS: MENEFEE

SURFACE @ POINT LOOKOUT 296'-MANCOS 534 @

GALLUP 1385'

SANTA FE RAILROAD # 10

30-031-20003 SEC. 07,T17N,R8W MCKINLEY, NM

PROPOSED P & A PROCEDURE

- ** PREPARE LOCATION
- ** MIRU PLUGGING EQUIPMENT, TIH WITH 2 7/8" TBG. TO PBTD @ 1583' LOAD CASING WATER AND CIRCULATE HOLE CLEAN, MIX AND PUMP 127 SXS. CLASS "B" CMT. AND SPOT BALANCED PLUG AT 500'-1583', POH WITH TBG., SECURE WELL, WOC OVERNIGHT
- ** CREW TO LOCATION, CONDUCT SAFETY MEETING, TIH WITH TBG. TAG TOC AT 500', IF TOC MEETS NMOCD REQUIREMENTS PROCEED TO PROCEDURE "A" IF THE TOC DOES NOT MEET NMOCD REQUIREMENTS PROCEED TO PROCEDURE "B"

PROCEDURE "A"

- ** PRESSURE TEST CASING TO 500 PSIG TO ASCERTAIN MECHANICAL INTEGRITY, POH WITH TBG., MIRU WIRELINE TRUCK PERF CASING AT 346', RIG DOWN WIRELINE TRUCK
- ** ESTABLISH RATE INTO PERFS AT 346' AND CIRCULATE OUT BRADEN HEAD UNTIL WATER CLEANS UP, MIX AND PUMP SUFFICIENT CEMENT VOLUME TO FILL 5 1/2" CASING AND ANNULUS BETWEEN 5 1/2" X 8 5/8" CASING FROM SURFACE TO 346', (APP. 111 SXS)
- ** RIG DOWN PLUGGING EQUIPMENT, ASCERTAIN HOLE TO BE STABLE, TOP OFF CASING IF NECESSARY, INSTALL P&A MARKER, RIG DOWN AND MOVE ALL EQUIPMENT
- ** RESTORE LOCATION

PROCEDURE "B"

- ** MIX AND PUMP SUFFICIENT CEMENT TO ESTABLISH A SATISFACTORY TOC, CEMENT WILL BE PUMPED THROUGH TBG AND A BALANCED PLUG WILL BE ACHIEVED, POH WITH TBG WOC
- ** TIH WITH TBG, TAG TOC AND THEN PROCEED TO PROCEDURE "A"