Form 3160-5 (June 1990)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

Lease Designation and Serial No.

6. If Indian, Allottee or Tribe Name

## <sub>/(1)</sub> NOO-C-14-20-5200

Navajo Allotted

SUNDRY NOTICES AND REPORTS ON WEL
-----------------------------------

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. O Farmington, NIM

Use "APPLICATION FOR PERMIT - - " for such proposals

7. If Unit or CA, Agreement Designation

SUBMIT IN TRIPLICATE 1. Type of Well Gas Well Other 2. Name of Operator **Redwolf Production, Inc.** 3. Address and Telephone No. P. O. Box 5382, Farmington, NM 87499

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

930' FSL & 800' FWL

**Section 15, T25N, R11W** 

Lost Wapiti 15 No. 13

9. API Well No.

Well Name and No.

AH IA

30-045-26846

10. Field and Pool, or Exploratory Area

Bisti Lower Gallup

11. County or Parish, State

San Juan County, NM

12.	CHECK APPROPRIATE BOX(s) TO	R DATA			
	TYPE OF SUBMISSION	TYPE OF ACTION			
	Notice of Intent	x	Abandonment		Change of Plans
	· ·		Recompletion		New Construction
	X Subsequent Report		Plugging Back		Non-Routine Fracturing
			Casing Repair		Water Shut-off
	Final Abandonment Notice		Altering Casing		Conversion to Injection
			Other	F	Dispose Water

(505) 326-4125

(Note: Report results of multiple completions o Well Completion or Recompletion Report and Lo

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this

Redwolf Production, Inc. plugged and abandoned the subject well on 5/2/03 as follows:

- 1. Set cast iron bridge plug at 4845' and cap with 21 sx plug from 4845' to 4658'.
- 2. Place 18 sx plug from 3355' to 3196'.
- 3. Place 19 sx plug from 2063' to 1897'.
- 4. Place 50 sx plug from 1283' to 840'.
- 5. Place 56 sx plug from 471' to surface.
- 7. Pumped 62 sx down bradenhead and topped off 5 1/2" casing with 12 sx.

	***				
14. I hereby certify that the foregoing is true and correct					
Signed Dava J. Delevent	Title	Vice-President	Date	5/9/2003	
(This space for Federal or State office)		CCEPTED FOR RECORD			
Approved by	Title	MAY 13-2003			
Conditions of approval, if any:			ARimine Smh	urriu	