

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

Sundry Notices and Reports on Wells

2006 JUL 25 AM 4 44

1. **Type of Well**
GAS

2. **Name of Operator**
CONOCOPHILLIPS

3. **Address & Phone No. of Operator**

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. **Location of Well, Footage, Sec., T, R, M**

Unit K (NESW), 1450' FSL & 2140' FWL, Ssec. 12, T25N, R5W, NMPM

5. **Lease Number**
JIC 145
6. **If Indian, All. or Tribe Name**

7. **Unit Agreement Name**

8. **Well Name & Number**
Jicarilla K #17

9. **API Well No.**
30-039-20433

10. **Field and Pool**
Basin Dakota

11. **County and State**
Rio Arriba Co., NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action	
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection

13. Describe Proposed or Completed Operations

6/28/06 MIRU A Plus #4. Pumped 50 bbls down tbhg to kill well. ND WH, NU BOP – test, OK. TOH w/tubing. RU WL. RIH w/gauge ring to 7414'. POOH. RIH w/CIBP & set @ 7414'. POOH. Mix 5 sx Type III cement. Make 2 dump bailer Runs & set cement **Plug #1** 7414' – 7374'. POOH. LD dump bailer & RD WL. Swabbed well. POOH. Load hole. Pumped **Plug #2** w/20 sx Type III cement – 6376- 6270'. Est. TOC w/required excess 6082'. LD 10 juts. WOC. 7/5/06 TIH w/tbg & tagged TOC @ 5648'. LD tbhg to 5420'. RU WL & set CIBP @ 5420'. RD WL. Load hole & pumped **Plug #3** w/37 sx Type III cement – 5420' – 4875'. LD tbhg to 4866'. TOH WOC. 7/6/06 TIH & tagged TOC @ 4847'. LD tbhg to 4127'. RU WL & set CIBP @ 4127'. Load csg & PT to 800# - OK. Pumped **Plug #4** w/11 sx Type III cement – 4127- 3965'. LD tbhg to 3357'. Load csg – pumped **Plug #5** w/50 sx Type III - 3357' – 2620'. LD tbhg to 1509'. Load hole & pumped **Plug #6** w/11 sx Type III cement - 1509' – 1347'. LD tbhg. RU WL & perf'd @ 344' – 3 holes. RD WL. Load hole & circ. out BH. Pumped **Plug #7** (surface plug) w/107 sx Type III cement. Circ. good cement out BH. ND BOP, Cut off WH. & installed Dry Hole marker w/30 sx Type III cement. RD & released rig. Well now P&A'd.

14. I hereby certify that the foregoing is true and correct.

Signed Patsy Clugston Patsy Clugston Title Sr. Regulatory Specialist Date 7/24/06

(This space for Federal or State Office use)

APPROVED BY _____ Title _____

Date _____

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

ACCEPTED FOR RECORD

AUG 02 2006

FARMINGTON FIELD OFFICE

NMCCD