In Lieu of
Form 3160
(June 1990)

UNITED STATES DEPARTMENT OF INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

SUNDRY NOTICE	AND REPORTS	ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION TO DRILL" for permit for such proposals

 Lease Designation and Serial No. SF-078762

2006 JUL 10 PM 12 31

If Indian, Allottee or Tribe Name

			Γ	
	SUBMIT IN TRIPLICATE	RECEIVED	7.	If Unit or CA, Agreement Designation ROSA UNIT
1.	Type of Well Oil Well X Gas Well Other	890 TEAT	8.	Well Name and No. ROSA UNIT #351
2.	Name of Operator WILLIAMS PRODUCTION COMPANY	AUG 2006	9.	API Well No. 30-039-26296
3.	Address and Telephone No. PO BOX 3102 MS 25-2, TULSA, OK 74101 (918) 573-6254		10.	Field and Pool, or Exploratory Area BASIN FRUITLAND COAL
4.	Location of Well (Footage, Sec., T., R., M., or Survey Description 1260' FSL & 1725' FWL, SE/4 SW/4 SEC 11-T31N-R05W	ption	11.	County or Parish, State RIO ARRIBA, NM

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent	Abandonment	Change of Plans	
	Recompletion	New Construction	
X Subsequent Report	Plugging Back	Non-Routine Fracturing	
• •	Casing Repair	Water Shut-Off	
Final Abandonment	Altering Casing	Conversion to Injection	
	Other Pumping Unit & Rod Installation	Dispose Water	
		(Note: Report results of multiple completion	
		on Well Completion or Recompletion Report	
		and Log form.)	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

 $\underline{05-10-2006}$ MIRU, NU w/ pump & flow back tank. Bled and kill w/ form wtr. ND xmas tree, NU BOP. Unland tbg, remove tbg hanger. TOOH w/ tbg, tag @ 3593' = 2' fill. NU air pack, broke circulation w/ 10 bph air/soap/corrosion inhibitor. Circulate to PBTD @ 3595'. Circulated clean, made soap sweeps, coffee ground coal recovered. Measured out of hole with 2 %" tbg, recovered 114 jts 2 %" tbg, tbg in good condition, SDFN.

<u>05-11-2006</u> Bled down & kill w/ prod wtr. Move in & rig Dyna Coil equip. TIH w/ mud anchor - f-nipple w/ exp chk on 27/8" prod tbg - strapped 1/4" stainless steel capillary chem injection tubing to outside of prod tbg. Install new chem adapted tbg hanger. Land tbg. ND w/ BOP. NU w/ new companion flange adapted for chem injection. Rig & TIH w/ new pump and rods - picked rods up in singles. Dressed 11/4" polished rod w/ liner - stuffing box – load cell & rod rotator. Space pump and filled w/ wtr. Pressure test @ 500 psi w/ rig pump. Stroked pump to 500 psi w/ pulling unit - good pump action. NU w pump jack and hung on for prod. Load out w/ rig tools, LD rig mast, clean loc, ready for production department, crew on location to connect flow line. Turn well to the production department. Release rig @ 1900 hrs, 5/11/06.

14.	I hereby certify that the foregoing is true and correct				
	Signed Tracy Ross	Title Sr. Production Analyst	Date	July 3,	ACCEPTED FOR RECORD
	(This space for Federal or State office use)				THE POT HECORD
	Approved by	Title		Date _	AUG 0 8 2006
	Conditions of approval, if any:				FARMINGTON FIBLD OFFICE
	8 U.S.C. Section 1001, makes it a crime for any person known to representations as to any matter within its jurisdictive		ent or agenc	y of the Un	