

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator
BURLINGTON
RESOURCES OIL & GAS COMPANY LP

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-3700

4. Location of Well, Footage, Sec., T, R, M
1010' FNL, 810' FEL, Sec. 12, T-27-N, R-10-W, NMPM

5. Lease Number
NMAB-077874
6. If Indian, All. or
Tribe Name
7. Unit Agreement Name

Well Name & Number
Hanks #13
API Well No.
30-045-06720
10. Field and Pool
Fulcher Kutz Pict Cliffs
Basin Dakota
11. County and State
San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other - Restimulate	

13. Describe Proposed or Completed Operations

6-12-03 MIRU. TIH w/gauge ring to 2351'. TOOH. TIH w/tbg plug, set @ 2250'. TOOH. PT tbg plug to 1500 psi/15 min, OK. Set second tbg plug @ 1000'. ND WH. NU BOP. Attempt to pull tbg. Pkr would not unset. SDON.

6-13-03 TIH w/free point. TOOH. TIH, shoot tbg @ 6547-6558'. TOOH. TIH w/chemical cutter. Chemical cut 2 3/8" tbg @ 6557'. TOOH w/2 3/8" tbg & tools. TIH w/fishing tools. Top of fish @ 6557'. SD for weekend.

6-16-03 Fishing. TOOH w/fish & fishing tools. SDON.

6-17-03 TIH w/4 1/2" CIBP & pkr; set CIBP @ 6620', set pkr @ 6540'. PT CIBP to 500 psi, OK. Reset pkr @ 2375'. PT csg to 500 psi, failed. Made multiple tool settings. Found holes in csg @ 4500-4560'. Reset pkr @ 2190'. Load annulus. PT csg to 500 psi, OK. SDON.

6-18-03 PT csg @ 0-2190' to 3000 psi/30 min, OK. TOOH w/pkr. TIH w/4 1/2" RBP & pkr; set RBP @ 4500', set pkr @ 4420'. PT csg to 500 psi, failed. Made multiple tool settings. TOOH w/pkr. SDON.

6-19-03 TIH w/pkr, set @ 4003'. PT csg to 500 psi below pkr, failed. Made multiple tools settings. TOOH w/RBP & pkr. TIH to 6599'. TOOH. TIH w/216 jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 6599'. ND BOP. NU WH. SDON.

6-20-03 RD. Rig released.

Procedure to plug and abandon well will be submitted by August 31, 2003.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Supervisor Date 7/24/03

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any: _____

ACCEPTED FOR RECORD

NMOC

ADMINISTRATIVE OFFICE
JUL 26 2003