FORM APPROVED

OMB No. 1004- 0137 Expires: March 31,2007

Navajo

5. Lease Serial No.

6. If Indian, Allottee, or Tribe Name

NOG 8707-1145 @

ocale	٠.	4111	^=	**	re-enter	## T	
osais	ΙO	arııı	or	to	re-enter	an	

Do not use this form for prop abandoned well. Use Form 3160-3 (APD) for such proposals.

SUNDRY NOTICES AND REPORTS ON WELLS

			<u>.</u>						
SUBMIT IN TR	7. If Unit or CA. Agreement Designation								
i. Type of Well Sas Well Gas	Other	RECE	IVED	8. Well Name and No.					
2. Name of Operator		070 FARM	NGTON NM	Navajo #158()					
·	9. API Well No.								
3a. Address	RIM Southwest Corpo	3b. Phone No. (inci	ude area code)	30-045-08536					
5 Inverness Drive East	, Englewood CO 80112	303-79	99-9828	10. Field and Pool, or Exploratory Area					
4. Location of Well (Footage, Sec.,	, R., M., or Survey Description)			Rattlesnake					
	11. County or Parish, State								
1980 \$	S & 1980 W (K) sec 12 '	T29N R19W	San Juan County, New Nexico						
12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA									
TYPE OF SUBMISSION		TY							
Notice of Intent	Acidize	 Dеереп	Production (S	tart/ Resume) Water Shut-off					
	Altering Casing	Fracture Treat	Reclamation	Well Integrity					
Subsequent Report	Casing Repair	New Construction	Recomplete	Other					
	Change Plans	X Plug and abandon	Temporarily A	bandon					
Final Abandonment Notice	Convert to Injection	Plug back	Water Disposal	1					
 13. Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 316-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.) A) RU A-Plus Well Service 8/10/06. Contact BLM Val Tamison @ 8:00 am with intention to P&A B) PU 5 1/2" scarper stacked out at 123'. Rotate w/ Tongs solid plug. TOH, Lay down Csg. Scraper. RIH open ended tag solid. TOH PU notched collar RIH, Tag at 123' Rotate and circulate. Circulate cement to surface. C) Received approval from Steve Mason at BLM and Wallace Ashley with Navajo Nation Minerals Department to spot plug from 123' to surface. D) Plug #1 Mix and pump 16 sxs.(21.1 cu ft.) 14.8 #/gal Type III cement to surface with good returns. E) RD BOP and screw off companion flange. Cut off casing and Rig down rig. F) Set Dry Hole marker w/ 25 sxs. cement 8/11/2006 well P&A'd G) Pull and cut off Anchors and clean location. 									
14. I hereby certify that the foregoing i	s true and correct.	•							
Name (Printed/ Typed) Kenneth	J Kundrik	Title	rations Engineer						
Signature Konno II	1 Kundak	Date		8/29/2006					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE									
The state of the s	The state of the s	A CONTRACTOR OF THE SECOND SEC	A STATE OF THE STA	A STATE OF THE PARTY OF THE PAR					

which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitiousor fraudulent statements or representations as to any matter within its jurisdiction.

Conditions of approval, if any are attached. Approval of this notice does not warrant o certify that the applicant holds legal or equitable title to those rights in the subject lease Office





Date