In Lieu of Form 3160
(June 1990)

UNITED STATES DEPARTMENT OF INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

SUNDRY NOTI	CE AND	REPORTS	ONWELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION TO DRILL" for permit for such proposals

Lease Designation and Serial No. NMSF-078764

6. If Indian, Allottee or Tribe Name

5.

11/10 n

	SUBMIT IN TRIPLICATE		If Unit or CA. Agreement Designation
1.	Type of Well Oil Well X Gas Well Other	OCT 2006	8 Ress UNIT #162B28
2.	Name of Operator WILLIAMS PRODUCTION COMPANY	The share of David David	9. API Ŵġll.No. 30-039-29845/
3.	Address and Telephone No. PO BOX 3102 MS 25-2, TULSA, OK 74101 (918) 573-6254		10. Field and Pool, or Exploratory Area BLANCO MESAVERDE
4.	Location of Well (Footage, Sec., T., R., M., or Survey Descrip 660' FSL & 660' FEL, SE/4 SE/4 SEC 30-T31N-R05W	otion)	11. County or Parish. State RIO ARRIBA, NM

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent	Abandonment	Change of Plans	
	Recompletion	New Construction	
X Subsequent Report	Plugging Back	Non-Routine Fracturing	
	Casing Repair	Water Shut-Off	
Final Abandonment	Altering Casing	Conversion to Injection	
	Other Completion	Dispose Water	
	<u> </u>	(Note: Report results of multiple completion	
		on Well Completion or Recompletion Report	
		and Log form.)	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

<u>07-17-2006</u> MIRU rig & all related equipment, RU BWWC, run cable from 6118' to 3500', RD WL, PU 2 3/8", 4.7#, J-55, EUE tbg & TIH w/ 3 7/8" bit. Bit @ 5984', SDFN.

<u>07-18-2006</u> Drl 15' of cmt from 6138' to 6153' PBTD, circulate clean, RU BJ, test 4.5" liner & 7" csg to 3500#, circulate hole w/ filtered prod water, spot 500 gallons 15% Hcl across Point Lookout, RD BJ, tally on TOH, ND BOP, NU frac Y, RU BWWC, perforate Point Lookout in acid top down w/ 3 1/8" SFG, .36" holes, 11 grm chg, 17" penetration, 1 spf, total of 56 holes. Top perforate @ 5712', bottom perforate @ 5996'. SDFN.

<u>07-19-2006</u> BD PLO w/ 1000 gals 15% HCL & 90 ballsealers, retrieve balls, frac PLO w/ 67781 gals slickwater, 9860# 14/30 lt prop, 4020# 20/40 brown sand, flush to top perf, set CIBP @ 5630' & test 3500#, perf C.H./Menefee 5478' to 5606' (40 holes), BD w/ 1000 gals 15% Hcl & 60 ballsealers, retrieve balls, frac C.H./Menefee w/ 66718 gals slickwater, 9320# 14/30 lt prop, 3000# 20/40 sand, flush to top perf, RD BJ, NU BOP, TIH w/ 50 stands, SDFN.

Continued on Back

14.	I hereby certify that the foregoing is true and correct			
	Signed	Title Sr. Production Analyst	Date	September 26, 2006 .
	(This space for Federal or State office use)			
	Approved by	Title		Date
	Conditions of approval, if any:			

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

CCEPTED FOR PECORD

OCT 0 5 2006

FARMINGTON FIELD OFFICE

<u>07-20-2006</u> Unload hole @ 3130', TIH to 5600', unload hole, clean out to CIBP @ 5635', drill out CIBP, RD P.S., TIH, tag @ 6130', circ w/ 12 bph mist, bypass mist circ air only & unload water off formation, bypass air, pull up into 7", turn well over to flowback hand, flow well on blooie line.

<u>07-21-2006</u> Flow well overnight on blooie line, TIH from liner top, CO 10' of fill to PBTD @ 6153', blow well around, pull 10 stds, flow natural 2.5 hrs, check for fill (6'), blow well around 2.5 hrs, pull up into 7", turn well over to flowback hand.

07-22-2006 Flow well on blooie line, recovered 156 bbls, total rec 516 bbls.

<u>07-23-2006</u> Flow well on blooie line overnight, TIH from L.T. to 6100', blow well around & unload wtr, land 2 3/8", 4.7#, J-55, prod tbg as follows: top down, tbg hanger, 191 jts, 1.78" S.N. @ 5984', 1 jt, exp mill @ 6017', ND BOP, NU tree & tst 2500#, pump off exp mill, press to 850# dropped to 400#, circ w/air .5 hr, turn well to production department, RD, release rig @ 1600 hrs.