Form 3160-5 (April2004)

UNITEDSTATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

FORMA	.PPROVED
OM B No	o. 1004-0137
Expires:	March 31, 200

5. Lease Serial No.

\sim	_^		4 4	^
-		78	7/1	h:

Do not use the	is form for proposals ell. Use Form 3160-3	to drill or to re (APD) for such p	-enter an ^{⊟⊄} roposals.	6. If Indian, Allot	tee or Tribe Name
SUBMIT IN TRI	PLICATE - Other ins	tructions on rey	%s& l eide U	7 Elf Unitor CA	'Agreement, Name and/or No
1 Type of Well	☐ Gas Well ☐ Other	£U	RECEIVE	8. Well Name an	i No.
2. Name of Operator			070 FARYING	- NEWBERRY	/ A 1M
ConocoPhillips Company	1		OTO PAIN THE	9. API Well No.	
3a. Address		3b. Phone No. (incl.	, ,	30-045-3338	
PO BOX 4289 Farmingto		(505)326-9	0597		ol, or Exploratory Area
4. Location of Well (Footage, Sec	c., T., R., M., or Survey Descr	iption)	}		averde/Basin Dakota
1940 SOUTH 660 EAST JL: I, Sec: 8, T: 31N, R: ⁻	12W			11. County or Pa SAN JUAN NM	irish, State
12. CHECK AF	PROPRIATE BOX(ES)T	O INDICATE NATI	JRE OF NOTICE, RI	EPORT, OR OTI	HER DATA
TYPEOF SUBMISSION		Т	YPEOF ACTION		
T371	Acidize	Deepen	Production (Sta	rt/Resume)	Water Shut-Off
X Notice of Intent	AlterCasing	FractureTreat	Reclamation		Well Integrity
Subsequent Report	Casing Repair	New Constructio	n Recomplete	X	OtherChange APD -
	Change Plans	Plug and Abando	n Temporarily Ab	andon	TD & 7" Csg
Final Abandonment Notice	Convert to Injection	Plug Back	☐ Water Disposal		Depth
the Cliffhouse formation 7141' KB. A revised drilli					
14. I hereby certify that the foreg Name (Printed/Typed)	going is true and correct	1			
Juanita Farrell		Title	Regulatory Spec	cialist	
Signature) 4 MM	Janul	Date	11/20/2006		
	THIS SPACE FOR	FEDERAL OR	STATE OFFICE	USE	
Approved by Original S	Igned: Stephen Mason		Title	Date	NOV 3 0 2006
Conditions of approval, if any, are certify that the applicant holds lega which would entitle the applicant	al or equitable title to those right to conduct operations thereon	ts in the subject lease	Office		
Title 18 U.S.C. Section 1001 and Tit States any false, fictitious or fraud	tle 43 U.S.C. Section 1212, mak fulent statements or representa	e it a crime for any perso ations as to any matter	n knowingly and willfully within its jurisdiction.	to make to any depa	tment or agency of the United

(Instructions on page 2)

ConocoPhillips

AFE #: API#: Network #: Elevation: Well Name: \$532,482 Newberry A 1M 6024 (GL) 10096250 WAN.CNV.5142 30-045-33386

SAN JUAN AREA: DRILLING WELL PLAN

	The second of th	100000		-
Location:	Sect:	8	T31N	R12W
	San Juan County, New Mexico	County, N	ew Mexico	
	1940	FSL	660	뛾
Lat:	36	deg	54.7140	minutes North
Long:	108	geb	6.706800	minutes West
Note: Deci	te: Decimal minutes (no seconds	no secon	ds)	

General Work Description: Drill, case and cement a new Meas Verde / Dakota Well Authorized:

Sundry notice: 7" casing must be set through the Cliffhouse, which is wet in this area in order to air drill to the Dakota.

Sundry notice: Geology has revised TD to 7141' KB (TD was originally planned at 7175').

Choke Cherry Canyon #1M (DK, 2006, .8 mi. E): F/4170' to 4500' slight gas kick, no report on difficulties w/SC, IC (2 stage job), PC, approximately 15 days of rig time @ location.

Newberry 12M (DK, 1997.1.3 mi NE): @ 5780' wet with oil & went on mud drilling, @ 5840' and 5930' lost returns (20% to 25% LCM used), lost circulation @ 129' TIH w/csg. pumped 150 bbls w/not returns, no returns on 1st or 2nd stage cmt job.

Culpepper Martin #16R (MV, 2006, 1 ml NE): no report on difficulties widniling, casing or cementing (IC-single stage, PC-single stage).

Weatherford 402E Float Collar Weatherford 1014M Omega Latch Down Plug
Hardware: Weatherford 329E Float Shoe
OD (in)
Production Casing
In the event of losses: 1) run stage tool 200' above Fruitland, 2) Pump tail sturry as first stage, 3) Pump lead sturry as second stage Weatherford 329E Float Shoe
Run centralizer 40' above & below stage tool
Install baffle in float collar
Additional Hardware (optional 2-stage): Weatherford Model 754 Hydraulic Stage Tool
d) one on first 7" collar just above 9-5/8 shoe e) one each on first two collars below wellhead
a) 10 above snoe on stop collar, and b) top of the 2nd, 4th, 8th, 8th, &10th joints
Centtralizers:
Weatherford 1305 Float Shoe
Conn. Hardware:
ntermediate Casing
4 Centralizers Weatherford Sawtooth Guide Shoe
9 5/8"
Surface Casing Nom. Dia.

Prepared by:

Alexander D. Galindo