UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RCVD JAN23'O'. OIL CONS. DIV. DIST. 3

	Ama 1181 1 Q DM 7: U l		
	2007 JAN 18 PM 2: 41	5.	Lease Number NM-01772-A
. Type of Well GAS	RECEIVED 210 FALAETTE MM	6.	If Indian, All. or Tribe Name
Name of Operator		7.	Unit Agreement Name
BURLINGTON RESCURCES OIL & GAS COMPA	NY LP	0	W 1137 0 37 1
Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700		 8.	Well Name & Number
		, 9 .	Neudecker 7F API Well No.
Location of Well, Footage, Sec., T, R, M Sec., TN, RW, NMPM			30-045-33847
		10.	Field and Pool
			Basin Dakota
Unit D (NWNW) 865' FNL & 1150' FWL, Sec	c. 13, T29N, R10W NMPM	11.	County and State San Juan Co., NM
2. CHECK APPROPRIATE BOX TO INDICAT	E NATURE OF NOTICE, REPOR	r, other	DATA
Type of Submission Type of Action			
Notice of Intent Abandonment		<u>x</u>	Other - Log
	New Construction Non-Routine Fracturing Water Shut off	<u>X</u>	Other - Log
Notice of Intent Abandonment Recompletion X Subsequent Report Plugging Casing Repair	New Construction Non-Routine Fracturing Water Shut off	<u>X</u>	Other - Log
Notice of Intent Abandonment Recompletion X Subsequent Report Plugging Casing Repair Final Abandonment Altering Casin	New Construction Non-Routine Fracturing Water Shut off Conversion to Injection ge ring. Tag PBTD @ 6687'. Ran CB	-	ot /
Notice of Intent Abandonment X Subsequent Report Plugging Casing Repair Final Abandonment Altering Casin 3. Describe Proposed or Completed Operations 2/5/06 RU Weatherford Wireline. RIH w/3.75" gau	New Construction Non-Routine Fracturing Water Shut off Conversion to Injection ge ring. Tag PBTD @ 6687'. Ran CB	-	ot/
Notice of Intent Notice of Intent X Subsequent Report Final Abandonment Final Abandonment The subsequent Report Final Abandonment Subsequent Report Final Abandonment Altering Casin The subsequent Report Altering Casin Altering Casin Subsequent Report Final Abandonment Altering Casin Notice of Intent Recompletion Plugging Casing Repair Altering Casin Subsequent Report Final Abandonment Final	New Construction Non-Routine Fracturing Water Shut off Conversion to Injection ge ring. Tag PBTD @ 6687'. Ran CB	-	ot /
Notice of Intent X Subsequent Report Thinal Abandonment Subsequent Report Final Abandonment Final Abandonment Altering Casing Repair Altering Casin Altering Casin RIH w/3.75" gau ontinued w/GR/CCL log to surface. Thinal Abandonment Thinal Abandonment Altering Casin Alteri	New Construction Non-Routine Fracturing Water Shut off Conversion to Injection ge ring. Tag PBTD @ 6687'. Ran CB	L from 6693	' to 1900'. TOC @ 1950'
Notice of Intent X Subsequent Report Third Abandonment X Subsequent Report Final Abandonment Subsequent Report Final Abandonment Altering Casing Repair Altering Casing Casing Repair Altering Casing A	New Construction Non-Routine Fracturing Water Shut off Conversion to Injection ge ring. Tag PBTD @ 6687'. Ran CB 2456 correct.	L from 6693	' to 1900'. TOC @ 1950'

ACCEPTED FOR REACHD

JAM 2 2 2007



