Form 3160-5 (April2004)

UNITEDSTATES

UNITEDSTATES									
DEPARTMENT OF	THE INTERIOR								
BUREAU OF LAND	MANAGEMENT								

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. FORMAPPROVED OM B No. 1004-0137 Expires: March 31, 2007

5. Lease Serial No.

NMNM03474CUD FEB9'07

6. If Indian, Allow of The Nation .

DIST. 3

SUBMIT IN TRI	PLICATE -	Other instru	uctions on r	evers	side.	Th. AFUAL	or CA/	Agreement, Name and/or No.	
1. Type of Well	☐ Gas Well	Other		_	RECEIVE	0 8. Well Na	me and	1 No.	
2. Name of Operator					TSANSUAN 29-6 UNIT 85M				
ConocoPhillips Company				•		9. API We			
3a. Address			3b. PhoneNo.			30-039-	2634	3	
PO BOX 4289 Farmington NM 87499 (505)326-9597			10. Field and Pool, or Exploratory Area						
4. Location of Well (Footage, Sec	c., T., R., M., o	r Survey Descrip	tion)					SAVERDE/BASIN DAK)T/
794 SOUTH 1848 EAST UL: O, Sec: 27, T: 29N, R: 6W				11. County or Parish, State RIO ARRIBA NEW MEXICO					
12. CHECK AF	PROPRIATI	E BOX(ES)TO	INDICATE N	ATURE	OF NOTICE, RI				
TYPE OF SUBMISSION				TYPI	EOF ACTION				
	Acidize	·	Deepen		Production (Sta	rt/Resume)		Water Shut-Off	
Notice of Intent	AlterCa	asing [FractureTrea	at	Reclamation	,	\Box	Well Integrity	
X Subsequent Report	Casing	-	New Constru		Recomplete			OtherAbandon Dakota	
X Subsequent Report	Change	•	Plugand Aba		Temporarily Ab	andon		zone	
Final Abandonment Notice		t to Injection	Plug Back		Water Disposal		-		
testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 11/06/06 MIRU Key Rig 64. ND WH NU BOP. Pull Tbg hanger. TOH 2 1/6" production tbg. RIH 77 jnts 2 1/16 and 168 jnts 2 3/8" tbg (work string). Tag fill at 7506'. Circ to fill @ 7525. Pump balance plug from 6000' to 7525' w/81 sx (95 cu ft - 17 bbl) Class G cmt w/.5% Halad 9, 0.2% HR. 11/10/06 Tbg string stuck. RU W/L & freepoint tool. Tag cmt inside tbg @ 5781'. Run freepoint tool, tbg free @ 5150. Cut tbg @ 5129'. POOH, stand back 2 3/8" tbg. Laydown 56 jts and cut-off jnt 2 1/6" tbg - left 21 jnts and cut-off jnt (650')in hole. 11/13/07-11/29/07 RIH w/fishing tools & tag TOF @ 5146'. Attempted to wash over pipe. POOH w/137' of 2 1/16" tbg. RIH w/ metal muncher mill & tag fish @ 5295'. Mill cmt and tbg from 5295'-5529'. C/O to 5550'. (Cement plug from 5550' to 7525') 11/30/06-12/04/06 RIH w/pkr and set @ 5547'. PT csg and cement to 500#/30 min. Good test. Test flow from MV perfs. Release & pooh w/pkr. RU W/L. Re-perf MV @ 5112' to 5527', 1 spf -13 holes. RIH w/pkr and set @ 4955'. RU to acidize. Pump 100 gal 15% HCL. RU swab tools & swab back acid. POOH w/pkr. 12/05/06 RIH w171 jnts 2 3/8" tbg and set @ 5178'. RDMO 12/05/06									
14. I hereby certify that the fore Name (Printed/Typed)	going is true an	nd correct							
Juanita Farrell			1	Title F	Regulatory Spec	cialist			
Signature	Jaires	e o	1		02/02/2007				
	THIS SP	ACE FOR	FEDERAL (OR ST	ATE OFFICE	USE			
Approved by				Tit			AC Date	CEPTED FOR RECORD	
Conditions of approval, if any, are	attached. Appr	oval of this notice	does not warrant		- in				
certify that the applicant holds legal or equitable title to those rights in the subject le				fice			FEB 0 7 2007		
which would entitle the applicant	to conduct ope	erations thereon.					FAR	MINGTON FIET TO OCCUPE	
Title 18 U.S.C. Section 1001 and Ti States any false, fictitious or fraud	de 43 U.S.C. So Julent statemer	ction 1212, make	it a crime for any ions as to any ma	person kr atter with	owingly and willfully in its jurisdiction.	to make to at	ıy dena	HINGTON FISH OFFICE	