RCVD APR18'07 OIL CONS. DIV.

Form 3160-5

UNITED STATES

DIST. 3

(February 2005)	DEPARTMENT OF THE INTERIOR	Expires: March 31, 2007
	BUREAU OF LAND MANAGEMENT	Sylvense Sprial No.
_	SUNDRY NOTICES AND REPORTS ON WELLS	6. If Indian, Allottee or Tribe Name

OIVID 140. 1004-0137	
Expires: March 31, 2007	
MANNAGES Serial No.	
5. If Indian, Allottee or Tribe Name	
RECEIVED	

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 2 If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8. Well Name and No. Oil Well Gas Well Other Water Source Well San Isidro No. 14-4 2. Name of Operator Pride Energy Company 9. API Well No 300-43-20701 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area PO Box 701950 Rio Puerco Tulsa, OK 74170-1950 (918) 524-9200 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 660 FNL & 660 FWL 11. Country or Parish, State Sandoval Co., NM Unit D, Sec. 14-20N-3W 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Production (Start/Resume) Water Shut-Off Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity New Construction Other Casing Repair ✓ Recomplete Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Plug Back Water Disposal Convert to Injection 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 8/19/02: Set CIBP @ 2626 ft. Spotted 35' cmt over CIBP. Ran mechanical integrity test - OK 11/22/05 Set CIBP @ 1000 ft. Spotted 20' cmt over CIBP. Tested to 1000# - OK. 11/22/05: Perforated Fruitland @ 827'-30' & 835'-48' 12/27/05: Acidized Fruitland w/ 1000 gal. Foam Frac'd w/ 78,000 # 20/40 sd. 1/05/06: Ran pump & rods. Put on pump to test. NOTE: AFTER TESTING, WELL PRODUCES ONLY WATER W/ TRACE OF GAS. SHUT-IN UNTIL THE WELL CAN BE USED AS A WATER SOURCE WELL FOR A PLANNED GALLUP WATERFLOOD. All CIBP'S MUST Be CAPPED W 35' CMT FOR PLASTATUS. 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) **Larry Miller** Title Engineer Date 03/28/2007 Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

(Instructions on page 2)

fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,

