Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103
District I	Energy, Minerals and Natural Resources		May 27, 2004 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II OH. CONCERNA TION DIVISION		30-039-29754	
District III OIL CONSERVATION DIVISION District III 1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 Sonta Fa NM 87505		STATE FEE 6. State Oil & Gas Lease No.	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505			o. State On & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Gooding
1. Type of Well: Oil Well Gas Well X Other Dry Hole			8. Well Number 1 RCUD MAY4'07
2. Name of Operator Lone Wolf New Mexico, LLC			9. OGRID Number OIL CONS. DIV. 232512
3. Address of Operator			10. Pool name or Wildch 151. 3
1125 17th Street, Ste. 2290 Denver, CO 80202		wildcat	
4. Well Location Unit Letter N : 1100' feet from the South line and 300' feet from the West line			
Section 29 Township 32-N Range 02E NMPM CountRio Arriba			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
8130 'GL			
Pit or Below-grade Tank Application or Closure Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water			
Pit typeDepth to Groundy Pit Liner Thickness: mi			enstruction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON A REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON			
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEIVIEN	1306
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
Lone Wolf New Mexico, LLC proposes to plug & abandon this well according			
to the following procedure:			
1) Move on location and rig up completion rig. Nipple up an 8 5/8"			
x 5 1/2" swedge and 5 1/2" tubinghead. Nipple up the BOP.			
2) Pick up a 4 3/4" bit and bit sub on 2 3/8" tubing and clean out to			
PBTD at 2084'. Mix mud to 50-60 visc. to keep the hole open. TOH and lay down bit and bit sub.			
3) TIH with open-ended 2 3/8" tubing to 2084' Spot a balanced plug			
rcon 2084 to 980' (100' above the Dakota top) with 320 sx (378 cu ft'			
or Type 5 cement with 1/4#/sk celloflake.			
4) POH to 500' and circulate the tubing clean. WOC 3 hrs. TIH and tag the cement top. Pump another plug as necessary.			
5) POH to 171'. Fill the open hole 50' below the casing shoe and the			
8 5/8" casing to surface with 55sx (65 cu.ft.) of Type 5 neat cement			
TOH and II.	II the hole with cem	ent as nece	essary. ,
6) Install dryhole marker Reclaim loc. per NMOCD/surf Owner specif. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-			
grade tank has been/will be constructed or closed schording to NMOCD guidelines \square , a general permit \square or an (attached) alternative OCD-approved plan \square .			
SIGNATURE TITLE Operations Manager DATE 5/2/07			
Type or print name Mike Benetatos E-mail addressmike@lonewolfop. Telephone No 720)904-6949			
For State Use Only Com			
APPROVED BY: / VI James TITLE PUTT OIL & GAS INSPECTOR, DIST, 80 DATE 5/15/07			
Conditions of Approval (if any):			

LONEWOLF OPERATING GOODING #1

