Form	3160-	5
(April	2004)	

## **UNITED STATES** DEPARTMENT OF THE INTERIOR

FORM A	PPROVED
OMB No.	1004-0137

BUKEAU OF LAND MAN	AGEMENT	Expires: March 31, 2007		
SUNDRY NOTICES AND REPO		5. Lease Serial No. Contract 459		
Do not use this form for proposals t∰	6. If Indian, Allottee, or Tribe Name			
abandoned well. Use Form 3160-3 (APL	) for such proposals.	Jicarilla Apache Tribe		
SUBMIT IN TRIPLICATE - Other Instructions	OUT OAD SANDELLE D	7. If Unit or CA. Agreement Name and/or No.		
1. Type of Well Oil Well X Gas Well Other	OTO FARMINGTON NI	8. Well Name and No.		
2. Name of Operator		Jicarilla 459 #4		
Black Hills Gas Resources, Inc.		9. API Well No.		
	Phone No. (include area code)	30-039-24307		
P.O. Box 249 Bloomfield, NM 87413	505-634-1111	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	East Blanco, Pictured Cliffs			
790' FNL, 1850' FEL Unit B Sec 19, T30N, R3W		11. County or Parish, State  Rio Arriba, NM		
12. CHECK APPROPRIATE BOX(S) TO INDICATE N	NATURE OF NOTICE, REPOR	I, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent Acidize Dee	epen Production ( St	art/ Resume) Water Shut-off		
	cture Treat Reclamation	Well Integrity		
		= :		
X Subsequent Report Casing Repair Nev	v Construction Recomplete	Other		
Change Plans X Plug	g and abandon Temporarily Ab	endon		
Final Abandonment Notice Convert to Injection Plug	g back Water Disposal			
Black Hills Gas Resources has plugged and abandoned this well as per the attached report dated May 23, 2007.  The Jicarilla Apache Nation Office of water Administration had indicated that it DID NOT want this well as a water source well.				
		RCVD JUN14'07		
		OIL CONS. DIV.		
		<b></b> -		
	-	DIST. 3		
14. I hereby certify that the foregoing is true and correct.				
Name (Printed/ Typed)	Title			
Loren Diede		Consultant (Agent)		
Signature	Date	8-Jun-07		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by	Title	Date		
Conditions of approval, if any are attached. Approval of this notice does not warra	ant or			
	теоп.	ACCEPTED FOR ASCO		
Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitiousor fraudulent statements or representations as to any matter within its jurisdiction.  (Instructions on page 2)				

## A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 \* fax: 505-325-1211

Black Hills Gas Resources, Inc. Jicarilla 459 #4

May 23, 2007 Page 1 of 1

790' FNL & 1850' FEL, Section 19, T-30-N, R-3-W Rio Arriba County, NM Lease Number: Contract 459 API #30-039-24307

Plug and Abandonment Report

Notified BLM & NMOCD on 5/17/07

### **Work Summary:**

5/17/07 MOL. SDFD.

- 5/18/07 RU rig. Well pressures: casing, 80 PSI; tubing, 10 PSI; and bradenhead, 0 PSI. Blow well down. NU BOP, test. Release packer and TOH with 2.375" tubing, total 123 joints 3784'. LD packer. TIH and set 4.5" DHS cement retainer at 3700'. Pressure test tubing to 1000 PSI. Load casing with 50 bbls of water. Circulate well clean with total 65 bbls of water. Attempt to pressure test casing, leak 1 bpm at 500 PSI. Plug #1 with CR at 3700', spot 44 sxs Type III cement (58 cf) inside the casing from 3700' to 3052' to isolate the Pictured Cliffs perfs and cover the Ojo Alamo top. PUH and WOC. Shut in well. SDFD.
- 5/21/07 Open up well, no pressures. TIH with tubing and tag cement at 3065'. Load casing with 22 bbls of water. Attempt to pressure test casing, leak 1 bpm at 500 PSI. Load bradenhead with 1 bbl of water. Pressure test bradenhead to 300 PSI, held OK. TOH with tubing. Perforate 3 squeeze holes at 2067'. RIH with 4.5" DHS cement retainer; set at 2031'. Pressure test tubing to 1200 PSI. Pumped 10 bbls of water ahead; no circulation out casing.

  Plug #2 with CR at 2031', mix and pump 33 sxs Type III cement (44 cf), squeeze 25 sxs below CR and outside 4.5" casing, ½ bpm at 600 PSI, with final rate ½ bpm at 1400 PSI; and leave 8 sxs above CR up to 1914' to cover the Nacimiento top.

PUH and WOC. TIH and tag cement at 1909'. Load casing with 5 bbls of water. Attempt to pressure test casing, leak 1 bpm at 500 PSI. TOH with tubing and LD stinger. TIH with open ended tubing to 185'. Load casing with 3.5 bbls of water. Plug #3 with open ended tubing at 185', spot 20 sxs Type III cement (27 cf) inside the 4.5" casing from 185' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut in well and WOC. SDFD.

5/22/07 Open up well, no pressures. Casing on a vacuum. Load casing with 6 bbls of water. Estimate TOC at 375'. TIH with open ended tubing to 185'. Pressure test casing to 600 PSI, held OK.

**Plug #3a** with open ended tubing at 185', spot 20 sxs Type III cement (27 cf) inside the casing from 185' to surface, circulate good cement out casing valve. TOH and LD tubing. ND BOP. Dig out wellhead. Issue Hot Work Permit. Cut off wellhead. Mix 25 sxs Type III cement and install P&A marker. RD. MOL. R. Velarde, JAT BLM representative, was on location.

# Jicarilla 459 #4

#### P&A 5-23-2007

Cabresto Canyon; Ojo Alamo Ext./East Blanco Pictured Cliffs

790' FNL & 1850' FEL, NE, Section 19, T-30-N, R-3-W

Rio Arriba County, NM / API #30-039-24307

Today's Date: 3/2/07 Spud: 10/28/88

PC Completion: 1/4/89 OA Completion: 1/19/98

Elevation: 7143' GI

7155' KB

12.25" hole

Squeeze casing leaks from 1021' to surface with total 311 cf cement. (2003)

#### **WELL HISTORY**

May '03: Determine no or poor cement from 3000' to 1021'. Isolate casing leaks from 1021' to surface with total 311 cf.

**Feb '07**: Set RBP at 3340'. Re-sqz Ojo Alamo perforations with unknown amount of cement.

Nacimiento @ 2015'


Ojo Alamo @ 3205'

Kirtland @ 3430'

Fruitland @ 3575'

Pictured Cliffs @ 3750'

6.75" hole



TD 4165' PBTD 3340'