Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	APPROVED No 1004-0137
	March 31, 200
Lanca Camal Ma	

5	Lease Senal No
	NIM 04202

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.		NIVIO	102				
		6 If Indian, Allottee or Tribe Name					
SUBMIT IN TRIPLICATE- Other instructions on reverse side. 1. Type of Well		7 If Unit or CATA Component Name and Jan Ma					
		8 Well Name and No. Federal 11 No. 1 9 API Well No					
							3b Phone No (inclu
8801 S. Yale Ave., Suite 240 Tulsa, OK 74137-3535 918-492 4 Location of Well (Footage, Sec., T., R., M., or Survey Description)		910-492-3239	-3237		nd Pool, or Exploratory Area Fruitland Coal		
1140' FSL, 1360' FEL (SWSE		PM			or Parish, State		
				San Juan, NM			
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NATU	IRE OF NOTICE, I	REPORT, OF	R OTHER DATA		
TYPE OF SUBMISSION		Т	YPE OF ACTION				
Notice of Intent	Acidize	Deepen	Production (S	tart/Resume)	Water Shut-Off		
	Alter Casing Casing Repair	Fracture Treat New Construction	Reclamation		Well Integrity ✓ Other Fracture Treatment		
Subsequent Report	Change Plans	Plug and Abandon		bandon	Oulci		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal				
(CBL) from TD to surface LOGS SUBMITTED TO 5/30/07 MIRU BlueJet L perfs. MIRU Key Energy ball-off, exceeded max p 2:00 PM. MIRU BlueJet I	BLM & NMOCD by BLUEJE ogging @ 8:00 AM. Perforate @ 10:00 AM. Acidize perfs w/ ress, peaked @ 5,959#. Split 4- Logging @ 2:30 PM. GIH w/ r	T LOGGING with HSC gun from 750 gals 7.5% HCl, 14" csg above Brading gauge and junk b	2115-30', 2132-36', 2 breakdown perfs at 2 enhead. SD immediat basket, tag PBTD @ 2	138-44', 2148- ,160#. Drop 6 ely to assess d 292'. COH w/	50', 2184-2202', (1 SPF), 45 total 8 "Bioball" sealers, immediate amage. RDMO Key Energy @		
to retrieve CompBP, coultool in hole.	dn't move up or down. Attem	pted to set CompBP,	unsuccessful. Pulled v	wireline loose	from setting tool w/ 5000# leaving RCUD JUL 2'07		
PROCEDURE CONTINUED on next Sundry Notice				OIL CONS. DIV.			
					DIST. 3		
14 I hereby certify that the fore Name (Printed/Typed)	going is true and correct						
John P. Carrett		Title	President				
Signature		Date		06/11/2007			
	THIS SPACE FOR	FEDERAL OR	STATE OFFICE	USE	ACCEPTED FOR RECOR		
Approved by			Title		Date IUN 2 9 2007		
Conditions of approval, if any, are							
certify that the applicant holds lega which would entitle the applicant t		in the subject lease	Office		FARMINGTON FILLU OFFICE		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction (Instructions on page 2)

Report PT on prod csy



February 2005)	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			5 Lease Serial	FORM APPROVED OMB No 1004-0137 Expires March 31, 2007	
Do not use t	NOTICES AND REF his form for proposals t yell. Use Form 3160-3 (o drill or to re-e	nter an	NM 0420	Allottee or Tribe Name	
SUBMIT IN TR	RIPLICATE- Other instr	ructions on rever	se side.	7 If Unit or 6	CA/Agreement, Name and/or No	
l Type of Well Oil Well Gas Well Other				8 Well Name and No.		
2 Name of Operator WEST LAF	RGO CORP.			Federal 9 API Wel	11 No. 1 1 1 1 1 1 1 1	
3a Address 3b Phone No (include area code) 8801 S. Yale Ave., Suite 240 Tulsa, OK 74137-3535 3b Phone No (include area code) 918-492-3239		area code)	30-045-32468 10 Field and Pool, or Exploratory Area Basin Fruitland Coal			
		· · · · · · · · · · · · · · · · · · ·				
1140' FSL, 1360' FEL (SWSI	E) Section 11, T28N-R9W, NMI	PM		11 County o	r Parish, State n, NM	
12. CHECK A	APPROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, RE	EPORT, OR	OTHER DATA	
TYPE OF SUBMISSION		TY	PE OF ACTION			
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Star Reclamation Recomplete Temporarily Abs		Water Shut-Off Well Integrity Other Fracture Treatment (Continued)	
	eted Operation (clearly state all perturectionally or recomplete horizontall					

Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)

MIRU Baker Fishing Tools @ 8:00 AM. GIH w/ Baker 4 1/2" Retrievable Bridge Plug (RBP) on 2-3/8" tbg, set RBP @ 1301'. COH w/ tbg. GIH w/ Baker 4- 1/2" Casing Spear hung from rig elevators, spear top jt of csg. Pull tension on csg, remove bradenhead ring and slips. Observe that split appears to be only 4 to 5' in length. Pull 10,000# tension on csg, apply LH torque and screwed off top jt of 4- 1/2" csg. COH and lay down damaged jt of csg. GIH w/ 1 jt 4- 1/2" 10.5#/ft J-55 new API STC csg, stab into 2nd jt, screw on w/ 1,500# torque. Pull 20,000# tension on csg string, reinstall slips & ring on bradenhead. Press test csg w/ rig pump to 2,800#, held steady for 30 min. Vaughn Oilfied Svc cut off csg above bradenhead, welded on 4- ½" bell nipple. Install WH, NU BOP. MIRU Four Corners Testing @ 2:00 PM. Press test csg above RBP to 3,800#, held steady for 30 min. RDMO Four Corners Testing @ 3:00 PM. GIH w/ retrieval tool on tbg, latch on Baker RBP @ 1301'. COH w/ tbg and RBP. GIH w/ overshot on tbg, latch on to rope socket on Weatherford CompBP setting tool. Pull CompBP uphole approx. 400', stuck @ 1100'. Pull 30,000# tension and shear setting tool loose from CompBP body. COH w/ tbg, overshot & setting tool.

6/4/07 GIH w/ new 3-7/8" blade bit & tbg, tag CompBP @ 1,100'. RU power swivel. Drilled out Weatherford 4- 1/2 " CompBP. COH w/ tbg & bit. Bit was plugged off w/ debris, cleaned out bit, GIH w/ bit & tbg, tag PBTD @ 2292', est. circulation and clean out hole for 1-1/2 hrs 6/7/07 MIRU Key Energy @ 7:00 AM. Acidize perfs w/ 420 gals 7.5% HCl, breakdown perfs at 550#. Frac treatment of Fruitland Coal commenced at 8:20 AM. Pumped gelled wtr Nitrogen foam with 20/40 Brady Sand proppant: Avg Treating Pressure: 1,771#; Avg. Treating Rate: 41 BPM; Total Fluid pumped: 838 bbls; Total N2: 1,205,251 scf; Total Sand: 257,620 lbs; ISIP: 1,190#. 6/8/07 Flowing thru 3/16" choke at 454 psig = 376 Mcfd. Flowing back gas & N2, no apparent wtr

-			KCVD JUL2'07 —— DIL CONS. DIV. —
14 Thereby certify that the foregoing is true and Name (Printed/Types) John P. Garrett	Title President		DIST. 3
Signature	Date	06/11/2007	4005
THIS SPA	CE FOR FEDERAL OR STATE OF	FICE USE	ACCEPTED POF FR
Approved by	Title	l n	JUN 2 9 2007

Office which would entitle the applicant to conduct operations thereon Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

Conditions of approval, if any, are attached Approval of this notice does not warrant or

certify that the applicant holds legal or equitable title to those rights in the subject lease

Title

Date

FARMINGTON FL