C. L. W. J. Co., mar Tan A.	0 C4-4 CNI M	!		Form C 103
Submit 3 Copies To Appropriate District Office Er	State of New Monergy, Minerals and Natu			Form C-103 May 27, 2004
District I 1625 N French Dr , Hobbs, NM 87240	<i>G</i> ₁ , and 1.444	2	WELL API NO.	
District II	OIL CONSERVATIO	N DIVISION	30-045-253	
1301 W. Grand Ave , Artesia, NM 88210 District III	1220 South St. Fr		5. Indicate Type of Le	, /
1000 Rio Brazos Rd, Aztec, NM 87410 District IV	Santa Fe, NM 8	37505	STATE	FEE 🗷
1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lea	ise No.
SUNDRY NOTICES A (DO NOT USE THIS FORM FOR PROPOSALS DIFFERENT RESERVOIR. USE "APPLICATION PROPOSALS.)		OR PLUG BACK TO A	7. Lease Name or Unit DAVIS GAS COM J	Agreement Name:
1. Type of Well:			8. Well Number	
Oil Well Gas Well G	Other	<u> </u>	9. OGRID Number	
2. Name of Operator XTO Energy Inc.			5380	C -
3. Address of Operator		·	10. Pool name or Wild	lcat
2700 Farmington Ave., Bldg. K.	Ste 1 Farmington, N	M 87401	BLANCO MESAVERDE /	OTERO CHACRA
4. Well Location				
Unit Letter F : 1480	feet from the NO	RTH line and	1450 feet from th	e <u>WEST</u> line
Section 26				County SAN JUAN
11.	Elevation (Show whether	DR, RKB, RT, GR, e	tc.)	
Pit or Below-grade Tank Application or C	losure 🗆		**************************************	
2it type Depth to Groundwater		h water well D	○ istance from nearest surface w	vater
Pit Liner Thickness: mil				
NOTICE OF INTENT ERFORM REMEDIAL WORK ☐ PL		REMEDIAL WORK	BSEQUENT REPOI	LTERING CASING [
EMPORARILY ABANDON 🔲 CH	IANGE PLANS	COMMENCE DRILL	.ING OPNS. 🔲 P	PLUG AND [NBANDONMENT]
	JLTIPLE DMPLETION	CASING TEST AND CEMENT JOB		BANDONMENT COD JUL3'07 OIL CONS. DIV.
THER: PLUG BACK CHACRA	X	OTHER:		DIST. 3
 Describe proposed or completed open of starting any proposed work). SEE or recompletion. XTO Energy Inc. proposes to pose. 	ERULE 1103. For Multipl	e Completions: Attac	h wellbore diagram of pro	pposed completion
	rug back the thatta to		ar in the fortowing	menner.
 MIRU PU. TOH w/tbg. Set cmt retainer @ 2209'. 	Snot a 27 ov Time Ti	T omt nlug incide	71 casing fr/21001	- 22091 Alux Co
3) Pressure test casing to 2	500 psig for 30 minute	es. Ps.	, commy 11/2109.	= 2205 . pows 80
4) Perforate Fruitland Coal :	- -		ate Fruitland Coal w	/111,000# sand.
5) Clean out. Install pumping	ng unit equipment.		,	
				-
hereby certify that the information above rade tank has been will ne syntructed or closed				
IGNATURE July C. Ter	<i>p</i> '.		OMPLIANHCE TECH_DA	
0			lly_perkins@xtoenerg	y.com
ype or print name HOLLY C. PERKINS	1	Demuitir Oil 9 Cr	•	e No. 505-324-109 0
or State Use Only		Deputy Oil & Ga	t #3	JUL 0 9 20
PPROVED BY Senditions of Approval if any	TI'	TLE DIGITIO	DAT	E
Conditions of Approval, if any:	- A:111 -	<i>u. f. ==</i>		
ibrit plat / Notrfy o	CD 24 Hrs to	WITNESS		b