submitted in lieu of Form 3160-5

UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells 797 19 -3 PN 3: 24			
	5.	Lease Number	
. Type of Well	6.	SF-078386-A If Indian, All. or	
GAS SACTION WELL SACTION WHI	0.	Tribe Name	
2. Name of Operator	7.	Unit Agreement Name	
BURLINGTON RESCURCES OIL & GAS COMPANY LP			
	 8.	Well Name & Number	
Address & Phone No. of Operator		Sunray G #2B	
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No.	
Location of Well, Footage, Sec., T, R, M		30-045-33908	
	10.	Field and Pool	
Unit D (NWNW), 585' FNL & 210' FWL, Section 22, T31N, R9W, NMPM			
Unit H (SENE), 1560' FNL & M' FEL, Section 21, T31N, R9W, NMPM		Basin Dakota/Blanco MV	
	11.	County and State	
		San Juan Co., NM	
2. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, Type of Submission Type of Action	OTHER 1	DATA	
	Other - casi	ng report	
X Subsequent Report Plugging Non-Routine Fracturing		RCVD JUL9'07	
Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection		OIL CONS. DIV.	
3. Describe Proposed or Completed Operations		<u> </u>	
/14/07 MIRU Aztec 673. Change out BOP. PT casing to 600# 30/min – good test. RIH w/8 ½" hole. Do ntermediate. Circ hole. RIH w/111 jts 7" 23# L-80 LT & C casing set @ 4624'. RU to cement. 6/23/07 to bbls FW. Pumped Scavenger 19 sx(57cf-10bbls)Premium Lite FM Cement w/3% CaCl2, .25 #/sx CoCl2.	pump pre-f	lush of 10 bbls FW/10 bbls N	
MS. Lead- Pumped 605 sx(1289cf-229bbls) Premium Lite FM Cement w/3% CaCl2, .25 #/sx Cello-Fail- Pumpd 101 sx(139cf-25bbls) Type III Cement. Dropped plug & displaced w/181 bbls FW. Bumpeturns. WOC for temp survey. /23/07 Notified Jim Lovato (BLM) that cement did not circ on 7" casing. Temperature survey was lotified Jim Lovato on 6/24/07 that TOC was at 360', verbal permission to proceed given. No remezed/07 RIH w/6 ½" bit. PT 7" casing to 1500# 30/min-good test. D/O cement & ahead to 7919' (TD). s 4 ½" 11.6# L-80 LT & C casing set @ 7919'. RU to cement. 6/29/07 Pumped pre-flush of 10 bbls getement w/.3% CD-32, .25 #/sx Cello-Flake, 1% FL-52, 6.25 #/sx LCM-1. Tail-pumped 231 Sx(457cf-taCl2, .4% Sodium Mtasilicat, .4% FL-52, .25 #/sx Cello-Flake, 5% LCM-1. Dropped plug & displace lug down @ 04:17 hrs 6/30/07. RD cementers. ND BOP. RR @ 7:15 hrs 6/30/07. T will be conducted by the completion rig & results shown on next report. — Pepar F Toc A	lake, .4% Fed plug to 2 s run to ve ediation re Td reached (H2O. Pun 81bbls) Pre d w/122 bb	4% FL-52, 5#/sx LCM-1, & L-52, 5 3/sx LCM-1, & .4% States @ 20:20 hrs 6/23/07. Lerify TOC. TOC found @ 36 equired at this time. I on 6/28/07. Circ hole. RIH was been seen as the compact of the seen with the seen with the seen with the seen with the seen as	
ail- Pumpd 101 sx(139cf-25bbls) Type III Cement. Dropped plug & displaced w/181 bbls FW. Bumpeturns. WOC for temp survey. 23/07 Notified Jim Lovato (BLM) that cement did not circ on 7" casing. Temperature survey wa otified Jim Lovato on 6/24/07 that TOC was at 360', verbal permission to proceed given. No rem /24/07 RIH w/6 ½" bit. PT 7" casing to 1500# 30/min- good test. D/O cement & ahead to 7919' (TD). s 4 ½" 11.6# L-80 LT & C casing set @ 7919'. RU to cement. 6/29/07 Pumped pre-flush of 10 bbls geternent w/.3% CD-32, .25 #/sx Cello-Flake, 1% FL-52, 6.25 #/sx LCM-1. Tail- pumped 231 Sx(457cf-taCl2, .4% Sodium Mtasilicat, .4% FL-52, .25 #/sx Cello-Flake, 5% LCM-1. Dropped plug & displace lug down @ 04:17 hrs 6/30/07. RD cementers. ND BOP. RR @ 7:15 hrs 6/30/07. T will be conducted by the completion rig & results shown on next report. — Repart Toc A	lake, .4% Fed plug to 2 s run to ve ediation re Td reached (H2O. Pun 81bbls) Pre d w/122 bb	4% FL-52, 5#/sx LCM-1, & L-52, 5 3/sx LCM-1, & .4% States @ 20:20 hrs 6/23/07. Lerify TOC. TOC found @ 36 equired at this time. I on 6/28/07. Circ hole. RIH was ped Scavenger 9 sx(27cf-5bt mium Lite HS FM Cement was 1.50 km 1.50	
ail- Pumpd 101 sx(139cf-25bbls) Type III Cement. Dropped plug & displaced w/181 bbls FW. Bumpeturns. WOC for temp survey. /23/07 Notified Jim Lovato (BLM) that cement did not circ on 7" casing. Temperature survey was otified Jim Lovato on 6/24/07 that TOC was at 360', verbal permission to proceed given. No remezed/07 RIH w/6 ½" bit. PT 7" casing to 1500# 30/min-good test. D/O cement & ahead to 7919' (TD). s 4 ½" 11.6# L-80 LT & C casing set @ 7919'. RU to cement. 6/29/07 Pumped pre-flush of 10 bbls getement w/.3% CD-32, .25 #/sx Cello-Flake, 1% FL-52, 6.25 #/sx LCM-1. Tail-pumped 231 Sx(457cf-taCl2, .4% Sodium Mtasilicat, .4% FL-52, .25 #/sx Cello-Flake, 5% LCM-1. Dropped plug & displace lug down @ 04:17 hrs 6/30/07. RD cementers. ND BOP. RR @ 7:15 hrs 6/30/07. T will be conducted by the completion rig & results shown on next report. — Repart Toc A 14. I hereby certify that the foregoing is true and correct.	s run to ve ediation re Td reached //H2O. Pun 81bbls) Pre d w/122 bb	.4% FL-52, 5#/sx LCM-1, & L-52, 5 3/sx LCM-1, & .4% States @ 20:20 hrs 6/23/07. Lerify TOC. TOC found @ 36 equired at this time. I on 6/28/07. Circ hole. RIH was been seen as the compact of the compact of the seen with the seen wit the seen with the seen with the seen with the seen with the see	
ail- Pumpd 101 sx(139cf-25bbls) Type III Cement. Dropped plug & displaced w/181 bbls FW. Bumpeturns. WOC for temp survey. /23/07 Notified Jim Lovato (BLM) that cement did not circ on 7" casing. Temperature survey wa otified Jim Lovato on 6/24/07 that TOC was at 360', verbal permission to proceed given. No rem/24/07 RIH w/6 1/4" bit. PT 7" casing to 1500# 30/min-good test. D/O cement & ahead to 7919' (TD). s 4 1/2" 11.6# L-80 LT & C casing set @ 7919'. RU to cement. 6/29/07 Pumped pre-flush of 10 bbls genent w/.3% CD-32, .25 #/sx Cello-Flake, 1% FL-52, 6.25 #/sx LCM-1. Tail-pumped 231 Sx(457cf-1aCl2, .4% Sodium Mtasilicat, .4% FL-52, .25 #/sx Cello-Flake, 5% LCM-1. Dropped plug & displace lug down @ 04:17 hrs 6/30/07. RD cementers. ND BOP. RR @ 7:15 hrs 6/30/07. T will be conducted by the completion rig & results shown on next report. — Repart Toc A: 14. I hereby certify that the foregoing is true and correct.	s run to ve ediation re Td reached //H2O. Pun 81bbls) Pre d w/122 bb	.4% FL-52, 5#/sx LCM-1, & L-52, 5 3/sx LCM-1, & .4% States @ 20:20 hrs 6/23/07. Lerify TOC. TOC found @ 36 equired at this time. I on 6/28/07. Circ hole. RIH was been seen as the compact of the compact of the seen with the seen wit the seen with the seen with the seen with the seen with the see	
Tail- Pumpd 101 sx(139cf-25bbls) Type III Cement. Dropped plug & displaced w/181 bbls FW. Bumpeturns. WOC for temp survey. 1/23/07 Notified Jim Lovato (BLM) that cement did not circ on 7" casing. Temperature survey was lotified Jim Lovato on 6/24/07 that TOC was at 360', verbal permission to proceed given. No remediately 724/07 RIH w/6 ½" bit. PT 7" casing to 1500# 30/min-good test. D/O cement & ahead to 7919' (TD). s 4 ½" 11.6# L-80 LT & C casing set @ 7919'. RU to cement. 6/29/07 Pumped pre-flush of 10 bbls get ement w/.3% CD-32, .25 #/sx Cello-Flake, 1% FL-52, 6.25 #/sx LCM-1. Tail-pumped 231 Sx(457cf-124Cl2, .4% Sodium Mtasilicat, .4% FL-52, .25 #/sx Cello-Flake, 5% LCM-1. Dropped plug & displace lug down @ 04:17 hrs 6/30/07. RD cementers. ND BOP. RR @ 7:15 hrs 6/30/07. T will be conducted by the completion rig & results shown on next report. — Repart Toe A	ake, 4% Fed plug to 2 s run to ve ediation re Td reached (H2O. Pun 81bbls) Pre d w/122 bb	2.4% FL-52, 5#/sx LCM-1, & L-52, 5 3/sx LCM-1, & .4% States and 20:20 hrs 6/23/07. Lerify TOC. TOC found @ 36 equired at this time. If on 6/28/07. Circ hole. RIH was been served by the compact of the states and the states are served by the state	