Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED
OM B No 1004-0137
Expires: March 31, 200

DEFARTMEN	Expues: March 31, 2007			
BUREAU OF L	5. Lease Serial No. 257 129 25 6. If Indian, Allottee or Tribe Name			
SUNDRY NOTICES	100, 15 61			
Do not use this form for particles abandoned well. Use Form	o. If Indian, Allottee or Imbe Name			
SUBMIT IN TRIPLICATE- (7 If Unit or CA/Agreement, Name and/or No			
1. Type of Well Gas Well		8. Well Name and No		
2. Name of Operator BP AMERICA PRODUCTIO		(SEE ATTACHED WELL LIST) 9. API Well No.		
3a. Address 200 ENERGY COURT, FARMINGTON, NM	3b. Phone No (inclusion 505 326 9425	ıde area code)	10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T, R, M., or Surve	y Description)			
(PLEASE SEE ATTACHED LIST OF WELL	S FOR LOCATION)		11. County or Parish, State	
			SAN JUAN COUNTY, NM	
12. CHECK APPROPRIATE I	BOX(ES) TO INDICATE NATU	JRE OF NOTICE, RI	EPORT, OR OTHER DATA	
TYPE OF SUBMISSION	T	YPE OF ACTION		
Notice of Intent Acidize Alter Casin		Production (State Reclamation	Well Integrity	
Subsequent Report Casing R	· -		Other EQUIPMENT REMOVAL	
Final Abandonment Notice Convert to	~	Temporarily Aba	andon REMOVAL	
Attach the Bond under which the work will be per	plete horizontally, give subsurface locat rformed or provide the Bond No. on file If the operation results in a multiple cor Notices must be filed only after all requi	tions and measured and true e with BLM/BIA. Require impletion or recompletion in	e vertical depths of all pertinent markers and zones. d subsequent reports must be filed within 30 days n a new interval, a Form 3160-4 must be filed once	
BP AMERICA PRODUCTION COMPAN thirty-nine (39) BP locations, as listed on the		to remove "disconnecte	ed" dehydrators, over the next 90 days, from	
Due to improved processes on specific well disconnected and have been placed at least dehydrators so that labor and transportati availability.	t 35 feet away from the wellhead to	o be safely removed. B	P requests at least 90 days to remove these	
If you have any questions or concerns, plea	ase contact Larry Schlotterback @	9 505 326 9425.		
Disconnec	Led equipm	ent rimst	be removed	
by Octob	Led equipmer 1, 2007	,	uil como, piv.	
14. I hereby certify that the foregoing is true and Name (Printed/Typed)	correct		DIST. 9	
Larry Schlotterback	Title	Field Environmental (Coordinator	

RCUD JUN27'07
OIL CONS. DIV.

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Larry Schlotterback

Title Field Environmental Coordinator

Signature Augustus Schlotterback

Title Field Environmental Coordinator

Title Date JUN 2 6 2007

Approved by

Title Date JUN 2 6 2007

Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Title 8 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency when United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

1

Equipment Removal Project Well Location List

Date of Report: 6/25/2007

Start Date: 7/1/2007 Removal Date by: 10/1/2007

	Location	Type of Equipment	Ser.#	Unit	Sec	Twn.	Rng .	Remarks	Removal Date
45-09800	Atlantic B LS 008-MV	Dehy.	3090	М	3	30	10	Dehy competely disconnected	
45-2544	Blanco Com 1 001A MV/DK	Dehy.	1426	Р	2	30	11	Dehy completely disconnected	
45-19375	Day B 001-MV	Dehy.	4966	А	17	29	8	Dehy completely disconnected	
45-26139	Elliott Annie L C 004E DK	Dehy.	28367	F	15	29	9	Dehy completely disconnected	
	Elliott GC B 001A MV	Dehy.	167990	Е	13	29	9	Dehy completely disconnected (4/10/2007)	
45.08910	Elliott GC G 001-MV*	Dehy.	33389	N	33	30	9	Dehy completely disconnected	
45-24431	Gartner A 008A	Dehy.	415383	Ε	3	29	8	Dehy completely disconnected	
45-24958	GCU 086E-DK	Dehy.	30320	Р	35	29	13	Dehy completely disconnected	
145-26338	GCU 157E-DK*	Dehy.	36271	Е	35	28	13	Dehy completely disconnected	
45-24250	GCU 172E-DK	Dehy.	31428	N	25	29	13	Dehy completely disconnected	
15-22749	Hardie LS 005A-MV	Dehy.	30222	D	23	29	8	Dehy completely disconnected	
49-08561	Heath GC B 001-MV	Dehy.	34K995	G	9	29	9	Dehy completely disconnected	
45-24192	Heath W D A 003A-MV	Dehy.	34K1662	С	17	29	9	Dehy competely disconnected	
45-2283	Hughes B 007A-PC/MV	Dehy.	34587	F	29	29	8	Dehy completely disconnected (3/21/07)	
45-24648	Hughes LS 099-MV*	Dehy.	32363	С	30	29	8	Dehy completely disconnected	
45-24055	Jones 005-DK	Dehy.	2536	Α	35	29	8	Dehy completely disconnected	
45-23826	Jones A 001-DK*	Dehy.	4952	D	35	29	8	Dehy completely disconnected	
45. 23850	Jones A LS 002A-MV #	Dehy.	31112	0	11	28	8	Dehy completely disconnected	
45-23852	Jones A LS 006A-MV	Dehy.	3025	Н	14	28	8	Dehy completely disconnected	
45-22833	Jones LS 001A-MV*	Dehy.	39037	J	35	29	8	Dehy completely disconnected	
45-22152	Jones LS 002A-MV	Dehy.	31016	D	35	29	8	Dehy completely disconnected	
45-22134	Leeper GC 001A-MV	Dehy.	859303603	С	34	32	10	Dehy completely disconnected	
45-02081	Lobato GC A 001 MV	Dehy.	34K1619	K	3	29	9	Dehy completely disconnected	
45-179240	Ludwick LS 017-PC	Dehy.	3343	В	29	30	10	Dehy completely disconnected	

Equipment Removal Project Well Location List

Date of Report: 6/25/2007

Start Date: 7/1/2007 Removal Date by: 10/1/2007

	Location	Type of Equipment	Ser.#	Unit	Sec	Twn	Rng	Remarks	Removal Date
45-24692	Mansfield A 001E-	Dehy.	1538	J	25	30	10	Dehy completely disconnected (5/7/2007)	
45-26544	McCulley LS 005M- <v< td=""><td>Dehy. (2)</td><td>95735</td><td>D</td><td>24</td><td>28</td><td>9</td><td>Dehy completely disconnected</td><td></td></v<>	Dehy. (2)	95735	D	24	28	9	Dehy completely disconnected	
45-82096	McEwen GC C 001-PC	Dehy.	30410	N	5	31	10	Dehy completely disconnected	
15-22795	Navajo Allotted GC B 001A-MV*	Dehy.	20262	0	36	28	9	Dehy completely disconnected	
45-27519	Neal A 001-FT	Dehy.	4338	L	33	32	11	Dehy completely disconnected (5/9/2007)	
45-25680	Price 004E-DK	Dehy.	3025	1	14	28	8	Dehy completely disconnected	
45-25009	Roelofs 003E-DK*	Dehy.	2200	Р	9	29	8	Dehy completely disconnected	
45-22704	Russell A 002A-CH/MV	Dehy.	4379	С	25	28	8	Dehy completely disconnected	
45-29248	Storey LS 001A-MV	Dehy.	101454	E	27	28	8	Dehy completely disconnected	
45-07047	Storey LS 004 PC/MV	Dehy.	414	1	15	28	8	Dehy completely disconnected	
-	Тарр 004E-DK*	Dehy.	3031	1,	15	28	8	Dehy completely disconnected	
45-22361	Vandewart A 001A - MV	Dehy.	2973	Р	11	29	8	Dehy completely disconnected	
45-08337	Vandewart A 005 #1	Dehy.	35561	Н	14	29	8	Dehy completely disconnected	
		Dehy.	10007	l	24	29	8	Dehy completely disconnected	
45-2003	Warren Com 002	Dehy.	11329	G	14	. 28	9	Dehy completely disconnected (5/9/2007)	