

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No 1004-0135
Expires March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT -" for such proposals.

SUBMIT IN TRIPLICATE

2007 AUG 22 AM 10:54
RECEIVED
070 FARMINGTON NM

5 Lease Designation and Serial No
JIC-37B

6. If Indian, Allotted or Tribe Name

Jicarilla Apache

7 If Unit or CA, Agreement Designation

8 Well Name and No

A New Dawn #2

9. API Well No.

30 039 22283

10 Field and Pool, or Exploratory Area

Basin Dakota

11. County or Parish, State

Rio Arriba

1 Type of Well

☐

Oil
Well

☒

Gas
Well

☐

Other

2 Name of Operator

Dugan Production Corp.

3. Address and Telephone No.

P.O. Box 420 , Farmington, NM 87499 (505) 325 - 1821

Location of Well (Footage, Sec , T , R., M., or Survey Description)

1610' FNL & 1120' FWL (SW/4 NW/4)

Unit E, Sec. 14, T24N, R5W, NMPM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒

Notice of Intent

☐

Subsequent Report

☐

Final Abandonment Notice

TYPE OF ACTION

☒

Abandonment

☐

Recompletion

☐

Plugging Back

☐

Casing Repair

☐

Altering Casing

☐

Other

☐

Change of Plans

☐

New Construction

☐

Non-Routine Fracturing

☐

Water Shut-Off

☐

Conversion to Injection

☐

Dispose Water

(Note Report results of multiple completion on Well Completion or Recompletion Report and Log form)

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work)"

RCVD AUG 27 '07

OIL CONS. DIV.

DIST. 3

2214'

Spot 150' Type 5 cement plug at 6752'. (Dakota top is at 6702').

Spot 150' Type 5 cement plug at 3970'. (Mesaverde top is at 3920').

Spot 217' (2432'-2215') Type 5 cement plug to cover PC @ 2382' and 50' above Fruitland @ 2265'.

Perforate 50' below surface casing set at 265'.

Pump Type 5 cement down production casing and circulate to bradenhead.

Set dry hole marker and clean up location.

See attached for additional plugs

Na is overballed inside 4 1/2" casing

14. I hereby certify that the foregoing is true and correct

Signed

John Alexander
John Alexander

Vice-President

Date

8/21/2007

(This space for Federal or State office use)

Approved by

[Signature]
Title

VE

Date

AUG 21 2007

Conditions of approval, if any.

The Jicarilla Apache Nation requires 45 days to evaluate this well beginning from August 22, 2007 in order to determine if they would like to assume ownership of the well. If the Jicarilla Apache Nation has not contacted your office before the end of the 45 days you may proceed with plugging operations.

**UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
FARMINGTON DISTRICT OFFICE
1235 LA PLATA HIGHWAY
FARMINGTON, NEW MEXICO 87401**

Attachment to notice of
Intention to Abandon:

Re: Permanent Abandonment
Well: 2 A New Dawn

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
3. The following modifications to your plugging program are to be made:
 - a) Place a cement plug from 5695' – 5595' to cover the Gallup top.
 - b) Place a cement plug from 3260' – 3160' to cover the Chacra top.
 - c) Bring the top of the Pictured Cliffs/Fruitland plug to 2164'.
 - d) Place a cement plug from 2112' – 1853' to cover the Kirtland/Ojo Alamo interval.
 - e) Place a cement plug from 599' – 499' to cover the Nacimiento top.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.