Form 3160- 5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR CENTER **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB No. 1004-0137

Expires March 31, 2007

Lease Serial No.

Do no aband	ot use this form for proposa oned well. Use Form 3160-3	als to drill or to re- B (APD) for such pr	nnterland Malla ppissan Field O	ACOS Indian, Allottee, or Tribe Name Jicarilla Apache Tribe 7. If Unit or CA. Agreement Name and/or No.
SUBMIT IN TR	7. If Unit or CA. Agreement Name and/or No.			
1. Type of Well Oil Well X Gas Well	Other			8. Well Name and No.
2. Name of Operator	The state of the s			Jicarilla 31-03-32 #1
Black Hills Gas Resources	, Inc.			9. API Well No.
3a. Address		3b Phone No. (inclu	*	30-039-25050
P.O. Box 249 Bloo	505-63	4-1111	10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description)			East Blanco Pictured Cliffs
1565' FSL & 795' FWL (NW SW) Unit L				11. County or Parish, State
	Sec 32, T31N, R3W	7		Rio Arriba, NM
12. CHECK APPROF	PRIATE BOX(S) TO INDICA	ATE NATURE OF	NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION		TY	PE OF ACTION	
X Notice of Intent	Acidize	Deepen	Production (S	Start/ Resume) Water Shut-off
	Altering Casing	Fracture Treat	Reclamation	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	Other
	Change Plans	Plug and abandon	Temporarily A	Abandon
Final Abandonment Notice	Convert to Injection	Plug back	Water Disposa	
If the proposal is to deepen direction	nally or recomplete horizontally, give	subsurface locations and	measured and true vert	posed work and approximate duration thereof. tical depths or pertinent markers and sands. sequent reports shall be filed within 30 days

Black Hills Gas Resources had notified the Jicarilla Apache Nation Water Administration regarding the use of this well bore for a water source well. They have declined this well and the P&A will be completed as follows: 1. MIRU A Plus Well Services coiled plastic tubing. 2. RIH with plastic tubing to 209' and circulate hole clean. 3. Mix and pump 15 sx (20 cu ft) Type III cement inside casing to surface. WOC and top off if needed. 4. Cut off well head, install P&A marker as per BLM stipulations.

following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has

> RCVD SEP 11'07 OIL CONS. DIV.

> > DIST. 3

14. I hereby certify that the foregoing is true and correct. Name (Printed/ Typed) Loren Diede	Title	Consultant (Agent)
Signature and I	Date	6-Sep-07
THIS SPACE FOR FE	DERAL OR STATE	OFFICE USE
Original Signed: Stephen Mason		QED 1 0 2007
pproved by	Title	Date SEP 1 C 2007
- · · · · · · · · · · · · · · · · · · ·		Date SEP 1 C 2007
pproved by	arrant or	Date SEP 1 C 2007

States any false, fictitiousor fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

determined that the site is ready for final inspection.)

Jicarilla 31-03-32 #1


Wellbore Diagram API # 30-039-25050

UNIT L, NW SW, Sec 32, T31N, R03W Rio Arriba, NM

Spud date: 2/05/1991

8/10/2007

Elev. GL= 7083' Elev. KB= 7093'



Jicarilla 31-03-32 #1

Proposed P&A Wellbore Diagram

API # 30-039-25050


UNIT L, NW SW, Sec 32, T31N, R03W Rio Arriba, NM

Spud date: 2/05/1991

9/6/2007

surf.

Elev. GL= 7083' Elev. KB= 7093'



PBTD=3960' ORIGINAL

TD=4120' KB