PN

"Submit 3 Copies To Appropriate District State of New Mexico Form C-103 March 4, 2004 Energy, Minerals and Natural Resources District I WELL API NO. 1625 N French Dr., Hobbs, NM 88240 District II 30-045-07734 OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. STATE | 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS O / O O 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN-ORDER BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM, C-101) FOR SUCH Gallegos Canyon Unit PROPOSALS.) 8. Well Number 1. Type of Well: 202 Oil Well Gas Well X Other 9. OGRID Number 2. Name of Operator **BP** America Production Company 000778 3. Address of Operator 10. Pool name or Wildcat **Basin Dakota** 4. Well Location feet from the North line and 1450 feet from the East Unit Letter 1050 Township 29N Range 12W NMPM San Juan County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 5334' GL Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached) Pit Location: UL Sect Twp Rng Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water \_\_\_\_\_ Below-grade Tank Location UL \_\_\_\_\_ Sect \_\_\_\_ Twp\_\_\_\_ feet from the line and feet from the 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ALTERING CASING □ COMMENCE DRILLING OPNS.□ **TEMPORARILY ABANDON** П PLUG AND CHANGE PLANS **ABANDONMENT** CASING TEST AND PULL OR ALTER CASING **MULTIPLE** COMPLETION **CEMENT JOB** OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 02/17/2006 MIRUSU. Blow down wellhead. NDWH. NU BOPs. TOH w/production TBG set @ 5892'. TIH w/RBP & set @ 5700'. Test RBP to 1000#. Test Ok. TOH w//RBP. TIH w/CIBP & set @ 5700'. RU & spot 12 sxs CMT from 5700' to 5600'. PU to 5530' & spot 51 sxs CMT from 5320' to 4870', PU & spot 18 sxs CMT from 2970' to 2870'. PU & spot 45 sxs CMT from 1300' to 920'. PU & spot 36 sxs CMT from 504' to surface. request permission to plug and abandon the subject well as per the attached procedure. Cut off wellhead. Installed P&A well marker & identification plate. 02/27/2006 RDMOSU. Location turned over to environmental group for surface restoration. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines 🗔, a general permit 🗖 or an (attached) alternative OCD-approved plan 🗖. SIGNATURE . TITLE Sr. Regulatory Analyst DATE 03/01/2006 Type or print name Mary Corley E-mail address: corleyml@bp.com Telephone No. 281-366-4491 PRESSULE Rework, SKATUS NOT (This Space for State Use) TITLE Deputy Oil &/Gas Inspector, DATESEP 1 1 2007 APPPROVED BY Conditions of approval, if any: SUPERVISOR DISTRICT # 3