

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO. **30-045-29225**
Indicate Type of Lease
STATE ☐ FEE ☒
State Oil & Gas Lease No.

Lease Name or Unit Agreement Name:

Woods Gas Com B

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
BP America Production Company Attn: **Toya Colvin**

8. Well No.

1

3. Address of Operator
P.O. Box 3092 Houston, TX 77253

9. Pool name or Wildcat
Kutz Pictured Cliffs, West

4. Well Location

Unit Letter **M** **1520** feet from the **South** line and **1150** feet from the **West** line

Section **7** Township **29N** Range **12W** NMPM **San Juan** County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
5476'

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: **P&A Subsequent Report** ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

2/6/07 NIPPLE DOWN WELLHEAD NIPPLE UP BOP AND RIG FLOOR SHUT WELL IN

2/7/07 TEST BOTH SET OF RAMS LOW 250 HIGH 1000 PSI HELD GOOD. RIG UP WIRELINE SET CIBP AT 1450'

2/8/07 RIG UP KEY CEMENTERS SET TWO CEMENT PLUGS PLUG #1 250' ABOVE CIBP 1450'- 1200' with 11 SXS CMT 15.50 PPG, YIELD 1.200 PLUG #2 334' TO SURFACE with 14 SXS of CMT 15.50 PPG, YIELD 1.200

2/9/07 NIPPLE DOWN RIG FLOOR AND BOP. HIGH DESERT DIG OUT CELLAR FIND BRADEN HEAD VALVE CHECK BRADEN HEAD VALVE WITH LEL ABOVE 10 WAIT UNTIL IT GOT TO ZERO CUT OFF WELLHEAD. FILL 3.5 ANNULAR TO SURFACE WITH READY MIX CMT. FROM 4-CORNERS MATERIALS. INSTALL P X A MARKER INSTALL P x A MARKER. RIG DOWN SERVICE UNIT. MOVE OFF LOCATION

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Toya Colvin* TITLE **Regulatory Analyst** DATE **02/12/2007**

Type or print name **Toya Colvin** Telephone No. **281-366-7148**

(This space for State use)

**Deputy Oil & Gas Inspector,
District #3**

APPROVED BY *Monica Kuehling* TITLE _____ DATE **10-10-07**

Conditions of approval, if any: