sübmitted in lieu of	Form 3160-5 UNITED STATES		
	DEPARTMENT OF THE INTERIOR		
	BUREAU OF LAND MANAGEMENT	BECEN/ED	
	Sundry Notices and Reports on	Wells	<del></del>
		700 101 -6 PM <b>3:.  </b>	Lease Number
			NMNM-012708
1. Type of Well GAS		070 Farmington, NN	If Indian, All. or Tribe Name
		7.	Unit Agreement Name
2. Name of Operator	N1		
BURLINGTO	S oil & gas company		
HESBURGE	OIL & GAS COMPANY	8.	Well Name & Number
3. Address & Phone N			Howell E #300
PO Box 4289, Far	mington, NM 87499 (505) 326-9	700 9.	<b>API Well No.</b> 30-045-26918
	Footage, Sec., T, R, M		Field and Pool
850'FNL, 1170'FEL	, Sec.14, T-30-N, R-8-W, NMPM		Basin Fruitland Coal
			County and State San Juan Co, NM
12. CHECK APPROPRIAT  Type of Submissio  Notice of  X_ Subsequen	Intent Abandonment Recompletion Plugging Back	f Action  Change of Pl.  New Construc  Non-Routine	ans tion Fracturing
Type of Submission Notice of X Subsequent Final Aba  13. Describe Propo 9/9/03 MIRU. 9/10/03 TOOH SN	Intent Abandonment Recompletion Lt Report Plugging Back Casing Repair	f Action  Change of Pl. New Construction Non-Routine Water Shut of Conversion to Conversion  BOP. SDON.  8" 4.7# J-55 tbg,	ans tion Fracturing ff o Injection  set @ 2706'.
Type of Submission Notice of X Subsequent Final Aba  13. Describe Propo 9/9/03 MIRU. 9/10/03 TOOH SN	Intent Abandonment Recompletion Plugging Back Casing Repair Altering Casin X Other -  sed or Completed Operations  TOOH w/pump & rods. ND WH. NU w/2-3/8" tbg. TIH w/85 jts 2-3 @ 2678'. ND BOP. NU WH. TIH w/	f Action  Change of Pl. New Construction Non-Routine Water Shut of Conversion to Conversion  BOP. SDON.  8" 4.7# J-55 tbg,	ans tion Fracturing ff o Injection  set @ 2706'.
Type of Submission  Notice of  X Subsequent  Final Aba  13. Describe Propo  9/9/03 MIRU.  9/10/03 TOOH  SN  OK	Intent Abandonment Recompletion Plugging Back Casing Repair Altering Casin X Other -  sed or Completed Operations  TOOH w/pump & rods. ND WH. NU w/2-3/8" tbg. TIH w/85 jts 2-3/8 @ 2678'. ND BOP. NU WH. TIH w/s. RD. Rig released.	Change of Pl.  Change of Pl.  New Construc  Non-Routine  Water Shut o  Conversion to  BOP. SDON.  8" 4.7# J-55 tbg,  pump & rods. PT &	ans tion Fracturing ff o Injection  set @ 2706'.
Type of Submission  Notice of  X Subsequent  Final Aba  13. Describe Propo  9/9/03 MIRU. 9/10/03 TOOH  SN OK	Intent Abandonment Recompletion Plugging Back Casing Repair Altering Casin X Other -  Seed or Completed Operations  TOOH w/pump & rods. ND WH. NU w/2-3/8" tbg. TIH w/85 jts 2-3 @ 2678'. ND BOP. NU WH. TIH w/3. RD. Rig released.	Change of Pl.  Change of Pl.  New Construc  Non-Routine  Water Shut o  Conversion to  BOP. SDON.  8" 4.7# J-55 tbg,  pump & rods. PT &	ans tion Fracturing ff o Injection  set @ 2706'. pump action,
Type of Submission  Notice of  _X_ Subsequent  Final Aba  13. Describe Propo  9/9/03 MIRU. 9/10/03 TOOH  SN  OK  14. I hereby certi  Signed Tammy	Intent Abandonment Recompletion Plugging Back Casing Repair Altering Casin X Other -  Seed or Completed Operations  TOOH w/pump & rods. ND WH. NU w/2-3/8" tbg. TIH w/85 jts 2-3 @ 2678'. ND BOP. NU WH. TIH w/3. RD. Rig released.	Change of Pl.  Change of Pl.  New Constructor  Non-Routine water Shut of Conversion to	ans tion Fracturing ff o Injection  set @ 2706'. pump action,

NMOCD

OCT 1 6 2003

FARMINGTON FIRLD OFFICE
BY