Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

5 Lease Serial

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				NM NM 33015 6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.	
I. Type of Well				78. Well Name and No. West Fork #1 9. API Well No.	
Name of Operator Coleman Oil & Gas, Inc.					
Sa. Address P.O. Drawer 3337		3b. Phone No. (include 505-327-0356	area code)	30-045-25632 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Basin Fruitland Coal		
940' FNL, 1560' FWL C, Section 14, T26N, R12W Latitude 36° 19' 33", Longitude 108° 05' 05"			11. County or Parish, State San Juan, New Mexico		
12. CHECK A	PROPRIATE BOX(ES) TO	INDICATE NATURI	E OF NOTICE, RE	EPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
✓ Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Star Reclamation Recomplete Temporarily Aba Water Disposal	Well Integrity Other	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

COLEMAN OIL & GAS, INC. WOULD LIKE TO REQUEST PERMISSION TO PERFORM A PRESSURE INTEGRITY TEST ON THE PRODUCTION CASING AND TEMPORARILY ABONDANDON THIS WELL, AS PER THE ATTACHED PROCEDURE. WITH YOUR APPROVAL WE ANTICIPATE HAVING A RIG AND COMPLETING THE WORK WITHIN THE NEXT 30 TO 60 DAYS.

> RCVD OCT 19'07 OIL CONS. DIV.

Must test CASING TO CIBP @ 5000

DIST. 3

14. Thereby certify that the foregoing is true and correct Name (Printed/Typed)						
	OPERATIONS ENGINEER					
Signature // MMM 1. Date	Detober	2007				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved by Original Signed: Stephen Mason	Title	Date OCT 1 8 20	27			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or						
certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office					
Title 18 USC Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any perso States any false, fictitious or fraudulent statements or representations as to anymatter with	n knowingly and willfully to make to a in its jurisdiction	any department or agency of the U	nited			

(Instructions on page 2)

Coleman Oil & Gas, Inc.

Pressure Test Production Casing

Friday, October 05, 2007

Well: Location: West Fork #1

940' FNL & 1560' FWL

Sec 14, T26N, R12W, NMPM

San Juan County, New Mexico

By:

Michael T. Hanson

Field:

Basin Fruitland Coal

Elevation: 6220' RKB

6173' GL

Lease:

NM 33015

Procedure:

Pressure Test Production Casing

- MIRU and POOH with Rods & Tubing.
- 2. RIH with Arrow Set IX Tension set packer and set @ ± 1450. Pressure test casing from 1450' to CIBP @ 1610' to 2500 psig with third party tester.
- 3. RIH and set Bridge Plug @ \pm 1360 feet. Pressure test casing to 3000 psig with third party tester. (Notify BLM and OCD to witness pressure test 24 hours prior to testing casing)
- 4. File Sundry with BLM to T&A well.

COLEMAN OIL GAS, INC. WEST FORK #1

