submitted in lieu of Form 3160-5 **UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT**

OIL CONS. DIV. NICT O

	Sundry Notices and Re		www.d	
1.	Type of Well GAS	RECENCED UCT 1 7 2007	5. 6.	Lease Number SF-078995 If Indian, All. or Tribe Name
2.	Name of Operator CONOCOPHILLIPS	Sureau of Land Management Farmington Field Office	7.	Unit Agreement Name San Juan 31-6 Unit
3.	Address & Phone No. of Op	erator	- 8.	Well Name & Number San Juan 31-6 Unit 50M
	PO Box 4289, Farmington, N	M 87499 (505) 326-9700	9.	API Well No.
4.	Location of Well, Footage, S Surface: Unit F (SENW), 25 Bottom: Unit F (SENW), 18	- 10.	30-039-30117 Field and Pool Basin Dakota Blanco Mesaverde	
Ċţ	N		11.	County and State Rio Arriba Co., NM
12.		OX TO INDICATE NATURE OF NOTICE, REPORT, O'	THER	DATA
	Notice of Intent	Abandonment Change of Plans <u>X Oth</u> Recompletion New Construction	er – Casir	ng
	X Subsequent Report	Plugging Non-Routine Fracturing		

13. Describe Proposed or Completed Operations

Final Abandonment

9/24/07 MIRU AWS 777. NU BOP. PT csg to 600psi for 30 mins on 9/28/07 - good test. RIH w/8 3/4" bit & tag TOC @ 278'. DO cmt & drill ahead to 3485'. Circ hole. RIH w/84jts 7" L-80 23# LTC csg & set @ 3474'. Circ hole. Pumped in preflush of 10bbls gel & 5bbls H2O. Pumped in Savenger 19sx (56cf-10bbls) w/3% CaCl, .25pps Cello-Flake, .4% FL-52, 5pps LCM-1 & .4% SMS. Followed w/LEAD 444sx (947cf-168bbls) Premium Lite w/3% CaCl, .25pps Cello-Flake, .4% FL-52, 5pps LCM-1 & .4% SMS. Followed w/TAIL 76sx (107cf-19bbls) Type III cmt w/ 1% CaCl, .25pps Cello-Flake & .2% FL-52. Displaced w/135bbls H2O. Bumped plug to 1565#. Circ 25bbls cmt to surface. Plug down @ 01:00am on 10/4/07. WOC. PT csg to 1500# for 30mins @ 09:30am on 10/4/07 - good test.

Water Shut off

Conversion to Injection

10/4/07 RIH w/6 ¼" bit & tag TOC @ 3430'. DO cmt & drill ahead to 7915' TD. TD reached 10/7/07. Circ hole. RIH w/185 its 4 1/2" L-80 11.6# LTC csg & set @ 7913'. Pumped in preflush of 10bbls chem wash & 2bbl H2O. Pumped in Scavenger 9sx (28cf - 5bbls) Premium Lite cmt w/.25pps Cello-flake, .3% CD-32, 1% FL-52 & 6.25pps LCM-1. Followed w/LEAD 315sx (624cf-111bbls) Premium Lite cmt w/.25pps Cello-flake, .3% CD-32, 1% FL-52 & 6.25pps LCM-1. Displace w/123bbls H2O. Bump plug to 1260#. Plug down @ 06:45am on 10/8/07. ND BOP. RD RR @ 13:00hr on 10/8/07.

PT will be conducted by completion rig and results reported on next report. TOC will be reported on next report.

Casing Repair

Altering Casing

		1								
14	T	howaher	a a subifur	44.04	44.0	formation	:-	4-max 0	~~ d	0.0 MM 0.04
14.		nereov	сегшіх	uat	Ine	foregoing	IN	Irue	ана	correct.
	_									

Tamatessim

 Tamra Sessions
 Title Regulatory Technician
 Date
 10/17/2007

(This space for Federal or State Office use)		
APPROVED BY	 Date	
CONDITION OF APPROVAL, if any:	Ŕ	ACCEPTED FOR RECORD
Itle 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to the United States any false, fictitious or fraudulent statements or representations as to any		CCT 2 4 2007