Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II		30-045-33815
1301 W. Grand Ave, Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
<u>District IV</u> 1220 S. St. Francis Dr , Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505		RCVD DEC 5'07
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR USE "APPLICA	CES AND REPORTS ON WELLS ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Martinez Gas Com J OIL CONS. DIV.
PROPOSALS.) 1. Type of Well: Oil Well G	as Well 🕅 Other 🗍	8. Well Number DIST. 3
		1 N
2. Name of Operator	OMD A NV	9. OGRID Number 000778
BP AMERICA PRODUCTION Co 3. Address of Operator	UMPANY	10. Pool name or Wildcat
P.O. BOX 3092 HOUSTON, TX	77079-2064	Basin Dakota & Blanco Mesaverde
4. Well Location		
	1860 feet from the South line and	1090 feet from the West line
Section 32	Township 32N Range 10V	
	11. Elevation (Show whether DR, RKB, RT, GR, e	
	6093'	
Pit or Below-grade Tank Application or	Closure	,
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water		
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls: Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INT PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐	PLUG AND ABANDON REMEDIAL WO	ORILLING OPNS. P AND A
OTHER:		eption to tbg Depth Requirement 🗵
	eted operations. (Clearly state all pertinent details,	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
REQUESTING EXCEPTION TO RULE 107 TUBING DEPTH REQUIREMENT of 250' ABOVE TOP OF THE		
LOWER PERFS	•	
WELL STATUS: SHUT IN		

Well was drilled July 2006 and produced Oct. 2006 open hole Dakota Formation 7321' – 7397'. MV was added		
July 2007. The open hole Dakota formation has caved in twice, part of a drill collar was lost in the hole and a		
portion of a bridge plug is also down there. BP has evaluated the wellbore and determined it is more effective to		
produce said well with tubing set higher in the hole then rule requirement. It is BP's assessment that waste will not		
be caused by producing this we	Il with tubing set @5168°.	
DD (6.11		
	ption to the tubing depth requirement.	
Should you have any questions	please call Jesse Gracia @281-366-1946	
		11.11.0
	bove is true and complete to the best of my knowle losed according to NMOCD guidelines □, a general permit	
grade tank has been will be constructed or e	iosed according to Minoep guidennes, a general per une	U of all (attached) afternative Octo-approved plan
SIGNATURE Cherry Hlava	TITLE Regulat	ory Analyst DATE 12/3/07
Type or print name Cherry Hlava	E-mail address: hlavacl@bp.com	Telephone No. 281-366-4081
For State Use Only		
Approximately all off	Deputy Oil &	Gas Inspector, DATE LEC 1 0 2007
APPROVED BY: [Mai]	TITLEDistri	ict #3 DATE 1 0 2007