Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

5. Lease Serial No. NMNM14973

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

abandoned well. Use Form 3160-3 (APD) for such proposals. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions_on,page:25 *** 1. Type of Well JAN 1 0 2008 8. Well Name and No. Dome Federal 7-27-13 # 2 Oil Well Gas Well Other 9. API Well No 130-045-23581 2. Name of Operator Maralex Resources, Inc. 3b. Phone No. (include areascode) Id Unic 10. Field and Pool or Exploratory Area 3a. Address P.O. Box 338 WAW Fruitland Sand PC Ignacio, CO 81137 970/563-4000 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 820 FSL: 1850 FEL Section 7-T27N-R13W 11. Country or Parish, State San Juan County, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Deepen Water Shut-Off __ Acidize Production (Start/Resume) Notice of Intent Alter Casing Reclamation Well Integrity Fracture Treat New Construction Casing Repair Recomplete ✓ Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Maralex Resources, Inc. plugged and abandoned the above-captioned well on 12/6/07 as follows: 12/03/07 MOL and RU. Check pressures: 110 PSI tubing and casing; blow down. Well flowing water out tubing. Pump 10 bbls of water down tubing to kill well. ND wellhead. Pull slips. Threads on wellhead for 5.5" wellhead. Remove wellhead. Install A-Plus 2875" wellhead. NU BOP and test. Fill the bradenhead annulus with 0.25 bbl water. Pressure test bradenhead to 300 PSI for 10 minutes. TOH and LD 42 joints 1" tubing. Note: tubing had scale. Pump 20 bbls water 2 bpm at 250 PSI down casing. Plug #1 mix 60 sxs Type III cement (80 cf) and pump down the 2.875" casing filling from PBTD to surface. Casing pressure increased up to 1500 PSI. SI well for 30 minutes. Open up well; no flow ND BOP. Found cement at surface. RD unit. 12/06/07 Issue Hot Work Permit. Monitor for gas around wellhead. Cut off wellhead. Found cement at surface in both the casing and 7" casing annulus. Mix 10 sxs Type III cement and install P&A marker. RD. MOL. RCVD JAN 15 '08 OIL CONS. DIV. DIST. 3 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Carla S. Shaw Title Production Technician Carle Atan Date 01/09/2008 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

NMOCD &

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,

fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)