Form 3160-5 5 BLM 1 File 1 - WBU WIOS (November 1983) (Formerly 9-331)  DEPARTMENT OF THE SINTERIOR refreshed to a BUREAU OF LAND MANAGEMENT	Expires Aukust 31, 1983
SUNDRY, NOTICES AND REPORTS ON WELLES 17 AM 2:  [Do not use this form for brobable to drul or to deepen or plue back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)	36. IF INDIAN, ALLOTTER OR TRIBE NAME
I. PARPINATORNIEW PIE	West Bisti Unit
DUGAN PRODUCTION CORP.	8. MARM OR LEAGE NAME West Bisti Unit
P.O. Box 420, Farmington, NM 87499	9. WELL EO.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface  1980' FSL & 660' FEL	10. FIELD AND FOOL, OR WILDCAT Bisti Lower Gallup 11. BRC.T.E. M. OR BLE. AND Sec. 27, T26N, R13W, NMPM
API# 30-045-05669-0000   15. ELEVATIONS (Show whether DF, ET, GR, etc.)	12. COUPTY OF PARISH 13. STATE  San Juan NM
6. Check Appropriate Box To Indicate Nature of Notice, Report, or	
TEST WITH SHOT-OFF PCLUOS LITER CASING WATER SHOT-OFF	RETAIRING WELL  ALTERING CASING
REPAIR WEYOLL COM. DIVO	abandonment*  is of multiple completion on Well pletion Report and Log form.)
Plan to plug and abandon with Class "B" cement lb./gal. mud as follows:	
Plug 100' inside 5%" casing 4882-4982 across Gall	
Perforate 100' below Mesa Verde (2734) @ 2834 . inside and outside of casing 2834-2634.	spoc 200. prug
Perforate 100' below Chacra (1594) @ 1694. Spot and outside of casing 1694-1494.	200' plug inside
Perforate 100' below Pictured Cliffs (1264) @ 1364 inside and outside of casing 1364-1164.	. Spot 200' plug
Perforate 50' below surface casing (215) @ 265. casing and circulate to surface, leaving product annulus full of cement.	
Place dry hole marker. Cut off casing and rig an	SEE ATTACHED FOR IChors CONDITIONS OF APPRO
signed Your Alexander Title Petroleum Engineer	APPROVED  AS ALZEISFOED
John Alexander  (This space for Federal or State office use)  APPROVED BY	JAN 16 1991  Manal Signed: STEPHEN MASOR
CONDITIONS OF APPROVAL, IF ANY:	AREA MANAGER

\*See Instructions on Rayage Side

NMOCD

70