

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-0 045-11490

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
Great Western Drilling Company

3. Address of Operator
7415 East Main ST. Farmington, New Mexico 87402

J. E. Decker

8. Well No.

2

9. Pool name or Wildcat
Blanco Mesa Verde

4. Well Location
Unit Letter N : 990' Feet From The South Line and 1850' Feet From The West Line
Section 12 Township 32-N Range 12-W NMPM San Juan County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
6293' Gr.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: Side Track Completion ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to move in rig on 10-27-95 rig up, drill out DV tool clean out to 5440', run CBL-CCL log and perf. PL05381-82, 5362-64, 5304-06, 5279-81, 5263-65, 5218-30, 5194-98, 5177-81, 5150-62, 5144-48, 5136-41--50' 1 SPF, acidize w/ 1500 gal 15% HCL and 100 balls, Frac w/ 100,000# 20/40 sand and 98,400 gal slick water. Set BP & Perf menefee 5071-75, 5065-70, 5054-61, 5031-33, 4983-85, acidize w/ 1500 gal. 15% HCL and 80 balls, frac w/ 50,000# 20/40 sand and 60,420 gal slick water. Set BP and perf lower cliffhouse 4808-11, 4795-4804, 4772-86, 4753-54, 4740-48, 4729-31, 4714-27--50' 1 SPF, acidize w/ 1500 gal. 15% HCL and 100 balls, frac w/ 75,000# 20/40 sand and 70,000# slick water. Set BP and pref upper cliff house 4647-52, 4642-44, 4636-37, 4543-48, 4524-26, 4517-19, 4508-12, 4492-97, 4455-58, and 4396-99 - 33' 1 SPF, acidize w/ 1500 gal 15% HCL and 66 balls, frac w/ 75,000# 20/40 sand and 70,000 gal slick water. Drill out BP's, swab back and test

OIL CON. DIV.
DIST. I

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John B. Heeling TITLE Div. Prod & Drlg. Supervisor DATE 10-26-95

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY [Signature] TITLE Dist. Supv. DATE 10/26/95

CONDITIONS OF APPROVAL, IF ANY: