In Lieu of
Form 3160
(June 1990)

UNITED STATES DEPARTMENT OF INTERIOR

MAY 0 5 2008

RCND HAY 13.08 nti cons. DIV.

DIST. 3

FORM APPROVED
Budget Bureau No. 1004-013
E

(June 199	BORDIO OF EARLY WHATEVER OF A SILE AND LABOR	wanajeme	Expires: March 31, 1993
Do not u	SUNDRY NOTICE AND REPORTS ON WELLS see this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICAT TO DRILL" for permit for such proposals	Field Calibe	Lease Designation and Serial No. NMSF-078771
	To British to, permit to their proposals	6.	If Indian, Allottee or Tribe Name
	SUBMIT IN TRIPLICATE	7.	If Unit or CA, Agreement Designation ROSA UNIT
1.	Type of Well Oil Well X Gas Well Other	8.	Well Name and No. ROSA UNIT #217A
2.	Name of Operator WILLIAMS PRODUCTION COMPANY	9.	API Well No. 30-039-29835
3.	Address and Telephone No. PO BOX 3102 MS 25-4, TULSA, OK 74101 (918) 573-3046	10.	Field and Pool, or Exploratory Area BASIN FRUITLAND COAL
4.	Location of Well (Footage, Sec., T., R., M., or Survey Description) 1500' FSL & 2260' FEL, NW/4 SE/4 SEC 11-T31N-R06W	11.	County or Parish, State RIO ARRIBA, NM

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Abandonment Notice of Intent Change of Plans Recompletion New Construction X Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Altering Casing Conversion to Injection Other PU Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is 13. directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Load out w/ rig & equip @ Ignacio 33-8 #27 & road to Rosa #217A & MIRU.

04-19-2008

TSIP 0 psi, CSIP 380 psi, ND WH, NU BOP, RU rig floor, tongs & equip. Pull tbg hanger & one stand. Tbg free, could not break out tbg hanger, cut off tbg, replaced w/ one jt new prod tbg. PU, RIH w/ 2 jts Yellowband to tag for fill. Tag fill @ 3,268' 1' fill. RU circ iron, broke circ w/ air. Unload well w/ air/soap/corrision inhibitor. CO 1' lite fines. TOOH, tallying 2 7/8" tbg, 2.28 ID seat nipple & muleshoe. Pumped 80 bbls produced coal wtr to kill well while POOH. Secure well & location. SDFWE.

Continued on attached sheets:

I hereby certify that the foregoing is true and correct Signed Rachel Lipperd	Title Engineering Technician	Date	April 30, 2008	ASCEPTED FOR NEXT.
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Title		Date	MAY 1 2 2008 FARMINGTON PRIZE OFFICE

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.




04-21-2008

SITP 0 psi, SICP 460 psi, blow well down to FB tank. WO mud anchor, F-nipple, standing valve, 103 jts 2-7/8" tbg, 6', 10' & 12' pup jts, test tbg every 20 stands to 1000 psi, all tested good. PU, MU & RIW w/ 2 7/8" mud anchor, 2.28 ID F-nipple w/ standing valve, 102 jts 2 7/8"tbg, 6' pup jt, 10' pup jt, 12' pup jt, & 1 jt 2-7/8" tbg, test tbg every 20 stands to 1000 psig, good test on all tbg. TOH w/ tbg to retrieve standing valve. RU Specialty Banding, attach 1/4" chemical string to production string from mud anchor to surface, total 3220' of 1/4" SS cap string. PU tbg hanger. RD Specialty Banding. Land tbg, tbg land as follows: 2-7/8" mud anchor, 2.28 ID F-nipple, 102 jts 2-7/8" production tbg, 6' pup jt, 10' pup jt, 12' pup jt, & 1 jt 2-7/8" tbg, EOT @ 3245', 24' off PBTD, 2.28 ID F-nipple @ 3219'. Secure well & location, SDFN.

04-22-2008

SICP 450 psi, blow well down to FB tank. PU MU & RIW as follows, Gas anchor, 2-1/2" X 1-1/4" X 8 X 12 RHAC pump, 3 3/4 X 1 1/4" sinker rods, 125 3/4" sucker rods, 1- 4', pony rod & 1 1/2" & 1 1/4" X 22' polish rod w/ 10' X 1-1/2" liner. Install stuffing box, seat pump & space out pump, load tbg w/ prod wtr, test tbg & pump to 500 psi, release press & stroke pump to 500 psig, test ok. RDMO to the Rosa #225A, 32 jts (1,002) new 2 7/8", 6.5# prod tbg transferred from Rosa #217A to Rosa #225A.

ROSA UNIT #217A BASIN FRUITLAND COAL



Hole Size	Casing	Cement	Volume	Top of Cmt
12-1/4"	9-5/8", 36#	155 sxs	215 cu.ft.	Surface
8-3/4"	7", 23#	450 sxs	910 cu.ft.	Surface
6-1/4"	5-1/2", 17#	Did Not Cmt		