| submitted | ın | lıeu | ot | Form | 3160-5 | | |
|----------------------------|----|------|------|------|------------|--|--|
| UNITED STATES | | | | | | | |
| DEPARTMENT OF THE INTERIOR | | | | | | | |
| | BU | REAU | OF I | LAND | MANAGEMENT | | |

.

•

X

RECEIVED

MAY 22 2008

| Sundry Notices and Reports on Wells | Bure Fa | au of Land Management armington Field Office |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|-------------------------------------------------|
| | 5. | Lease Number |
| . Type of Well GAS | 6. | SF-079382 If Indian, All. or Tribe Name |
| . Name of Operator | 7. | Unit Agreement Name |
| BURLINGTON RESOURCES OIL & GAS COMPANY LP | | San Juan 30-6 Unit POV |
| | <u> </u> | Well Name & Number |
| Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 | 9. | San Juan 30-6 Unit POW API Well No. |
| Location of Well, Footage, Sec., T, R, M Sec., TN, RW, NMPM | 10 | 30-039-24530 |
| Unit E (SWNW), 1485' FNL & 795' FWL, Sec. 24, T30N, R7W NMPM | 11 | Basin FRC |
| Notice of Intent Image: Abandonment Image: Change of Plans Subsequent Report Image: Plugging Image: Non-Routine Fracture Final Abandonment Image: Casing Repair Image: Water Shut-off Image: Altering Casing Image: Conversion to Injection | on | Other : MIT |
| 13. Describe Proposed or Completed Operations | | |
| urlington Resources intends to perform a MIT on the following well. Ple | ase see the | e attached procedure. |
| | | RCUD MAY 27 '08 |
| | | oil cons. div. |
| | | DIST. 3 |
| 4. I hereby certify that the foregoing is true and correct. | | |
| igned | ulatory Tech | n_Date <u>5/22/08</u> |
| This space for Federal or State Office use) PPROVED BY Original Signed: Stephen Mason Title | | Date MAY 2 3 2003 |
| CONDITION OF APPROVAL, if any: the 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of e United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. | | |
| | | |
| NWOCD | | , |

.

,

ConocoPhillips

San Juan 30-6 POW 1 Tubing Reconfiguration w/ MIT Latitude N 36° 48' 4"; Longitude W 107° 31' 40"

Prepared by: Kassadie Gastgeb 5/19/2008

RIG WORK NEEDS TO BE COMPLETED BY JULY 1, 2008 PER REGULATORY REQUIREMENTS.

Scope of work: Pull tubing, check for corrosion or scaling, perform MIT, reconfigure BHA, re-land packer and tubing.

Estimated rig days: 3

Well data

| API: | 300392453000 |
|---------------|---------------------------------------------|
| Location: | 1485' FNL & 795' FWL, Section 24, T30N, R7W |
| PBTD: | 3075' |
| TD: | 3080' |
| Perforations: | 2848'-3024' (FRC) |

Well history: The well was drilled in 1989 and never completed with cavitation or fracturing. There are two joints of 2-3/8" tubing in the hole. The well has always been a POW and never produced.

Artificial lift on well: None

Estimated reservoir pressure: 100 psi (FTC)

Well failure date: NA

Current rate: NA

Estimated post-remedial rate: NA

Earthen pit required: NO

Special requirements: Will need a regulatory witness for MIT, packer fluid provided by NALCO, and 2 hour chart for MIT. Also, ~3075' of 2-3/8" tubing will be needed.

Production engineer:Kassadie Gastgeb, Office: 324-5145, Cell: 739-6312Backup engineer:Ben Kelly, Office: 599-3432, Cell: 320-8099MSO:Darrell Savage, Cell: 505-320-2634Area foreman:Jim Work, Office: 324-5134, Cell: 320-2447

ConocoPhillips

San Juan 30-6 POW 1 Tubing Reconfiguration w/ MIT Latitude N 36° 48' 4"; Longitude W 107° 31' 40"

PBTD: 3075' KB: 12'

Procedure

RIG WORK NEEDS TO BE COMPLETED BY JULY 1, 2008 PER REGULATORY REQUIREMENTS.

- 1. Notify NMOCD 48 hours before rigging up on well.
- 2. Hold safety meeting. Comply with all NMOCD, BLM, and ConocoPhillips safety and environmental regulations. Test rig anchors prior to moving in rig.
- 3. MIRU. Check casing and bradenhead pressures and record them in Wellview. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCl if necessary. ND wellhead NU BOP. Release tubing from tubing hanger. TOOH with tubing and LD as follows:

From top to bottom

- (2) 2-3/8" 4.7#, EUE N-80 tubing joints
- (1) 2-3/8" F-Nipple (1.78" ID)

Visually inspect tubing string as it is being laid down. Report condition of tubing in WellView and scale, if any.

- 4. PU 2-3/8" workstring. TIH to tag for fill (PBTD @ 3075'). If fill level is above 3024', then clean out to PBTD. If not, proceed to step 5. TOOH.
- 5. Pick up RBP and Packer for 5-1/2" 15.5# K-55 casing and TIH, set RBP @ 2975' or deeper (must be within 50' of the top of coal perforation), set packer to test RBP to 500 psi for 10 min. Unset packer and perform MIT on the 5-1/2" casing, pressure test to 500 psi for 30 min, record test on a 2 hour chart, please contact Production Engineer with MIT results. Procedure may deviate from here.
- Latch on and retrieve RBP and TOOH. Lay down RBP and RIH with the tubing string as follows. Blow well dry with air package while tripping in hole. Set packer @ 2975' or deeper. Packer must be within 50' of top coal perforation. Tubing will be set at 3008'.

From bottom to top

- (1) Muleshoe/ Expendable Check
- (1) 2-3/8" F-Nipple (1.78" ID)

(1) 2-3/8" 4.7#, EUE J-55 tubing joint

\$

÷

(1) Packer for 5 1/2" 15.5# K-55 casing on the 2-3/8" tubing (set at 2975' or deeper)

(~95 jts) 2-3/8" 4.7#, EUE J-55 tubing joint

- 7. Set packer at 2975' (must be within 50' of the top of coal perforation). AD-1 tension set packer should set by turning to the left and pulling up. Load the back side with packer fluid provided by NALCO and pressure test to 500 psi for 10'3° min, if there is more than 10% bleed-off, reset packer and retest. Contact production engineering with results.
- 8. Pump off expendable check, and swab well dry.
- 9. ND BOP, NU wellhead. Notify lease operator that operation is complete. RDMO.



...

1