submitted	in	lieu	of	Form	3160-5			
UNITED STATES								
DEPARTMENT OF THE INTERIOR								
	BU	REAU	OF I	LAND	MANAGEMENT			

• •

RECIVED

SEP U3 2008

	Sundry Notices and Reports on Wells		SEP U3 2008
1.	Type of Well GAS	5.	Bureau of Lanibéranagsment Lease Numberanagsment NM-0546n Field Juice If Indian, All. or Tribe Name
2.	Name of Operator CONOCOPHILLIPS COMPANY	7.	Unit Agreement Name
3.	Address & Phone No. of Operator	8.	Well Name & Number Maddox WN Federal 1
	P.O. Box 4289, Farmington, NM 87499	9.	API Well No.
4.	Location of Well, Footage, Sec., T, R, M		30-045-09529
102	Unit H (SENE), 1650' FNL & 990' FEL, Section 13, T30N, R13W, NMPM	10. 11.	Field and Pool Basin Dakota County and State San Juan Co., NM

¥.

12. CHECK APPROPRIATE	BOX TO INDICATE NATURE OF NOTICE, J	REPORT, OTHER DATA
Type of Submission	Type of Action	
Notice of Intent	Abandonment Change of Plans	X Other – Plugback DK
	Recompletion New Construction	
<u>X</u> Subsequent Report	Plugging Non-Routine Fracturing	
	Casing Repair Water Shut off	
Final Abandonmen	Altering Casing Conversion to Injection	

13. Describe Proposed or Completed Operations

8/14/08 MIRU A-Plus 10 and plug back the Dakota per attached report and pressure test chart.

TA approved Var:1 9/1/09

> RCVD SEP 5 '08 OIL CONS. DIV. DIST. 3

NMOLD $-\tau/A$ ExPIRES O 14. I hereby certify that the foregoing is t			
Signed Jam Jessimo	Tamra Sessions	Title <u>Staff Regulatory Technician</u>	Date9/03/2008
(This space for Federal or State Office use)			
APPROVED BY	Title	Ľ	Date
CONDITION OF APPROVAL, if any: Title 18 U S C Section 1001, makes it a crune for any person knowingly the United States any false, fictuious or fraudulent statements or represen			ED FOR RECCAD
	NMO	CD SEI	⊃ 0 4 2008
		by particular	onfield office

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 * fax: 505-325-1211

ConocoPhillips **Maddox WN Federal #1** 1650' FNL & 990' FEL, Section 13, T-30-N, R-13-W San Juan County, NM Lease Number: NM-0546 API #30-045-09529 August 21, 2008 Page 1 of 2

Plugback Report

Notified BLM on 8/13/08

Plugging Summary:

08/14/08 MOL and RU. Lockout / tagout equipment on location. Check well pressures: casing and tubing, 840 PSI; bradenhead, 0 PSI. Lay relief lines to pit. Blow well down. ND wellhead. NU BOP, test. PU on tubing and remove donut. Tally and TOH with 216 joints 2.375" EUE 4.7# tubing, 6566' total. TIH with 4.5" DHS CR to 6476'. Hitting tight spots in casing from 4377' to 6476'. Load tubing with 40 bbls of water. Attempt to set CR at 6476', 6416', 6384', 6354', 6323'. Unable to set CR; felt like CR set but was slipping down hole. Stack out at 6536'. POH and LD setting tool. No retainer. Shut in well. SDFD.

08/15/08 Check well pressure: casing, 6 PSI; bradenhead, 0 PSI. No tubing in well. Blow well down. TIH with 4.5" CIBP and set at 6476'. TIH with tubing and plugging sub and tag CIBP at 6476'. Load the hole with 2 bbls of water. Circulate well clean with an additional 105 bbls of water. Attempt to pressure test casing, no test. Establish rate 1-1/4 bpm at 750 PSI.
Plug #1 with CIBP at 6476', spot 16 sxs Class B cement (19 cf) with 2% CaCl₂ inside casing above CIBP from 6476' up to 6270' to isolate the Dakota interval.
PUH with tubing. WOC. TIH and tag cement at 6392'. PUH to 5745'. Load the hole with 4 bbls of water. Attempt to pressure test casing, no test. Establish rate 1-1/4 bpm at 750 PSI.
Plug #2 spot 15 sxs Class B cement (18 cf) inside casing from 5745' up to 5551' to cover the Gallup top. TOH with tubing. WOC overnight.

08/18/08 Open well, no pressure. Tubing, casing and bradenhead on vacuum. TIH and tag cement low at 5643'. Load the hole with 4 bbls of water. Attempt to pressure test casing, no test. Establish rate 1-1/4 bpm at 750 PSI.
Plug #2a spot 15 sxs Class B cement (18 cf) with 2% CaCl₂ inside casing from 5643' up to 5449' to . cover the Gallup top.
PUH with tubing. WOC. TIH and tag cement at 5472'. PUH to 3678'. Load the hole with 5-1/2 bbls of water. Attempt to pressure test casing, no test. Establish rate 1-1/4 bpm at 750 PSI.
Plug #3 spot 25 sxs Class B cement (30 cf) inside casing from 3678' up to 3355' to cover the Mesaverde top.

TOH with tubing. Shut in well. WOC overnight.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499

505-325-2627 * fax: 505-325-1211

ConocoPhillips Maddox WN Federal #1

August 21, 2008 Page 2 of 2

Plugging Summary – Continued:

Open well, no pressure. Tubing, casing and bradenhead on vacuum. TIH and tag cement at 3498'. PUH to 2029'. Load hole with 5 bbls of water. Pressure test casing to 650 PSI, held OK for 5 minutes. POH with tubing and LD plugging sub. Perforate 3 holes at 2072'. Load the hole with 6 bbls of water. Establish rate into squeeze holes ³/₄ bpm at 1200 PSI. TIH with 4.5" DHS CR to 2029'. Load tubing with ¹/₂ bbl of water. Pressure test tubing to 1500 PSI, held OK. Finish setting CR at 2029'. Establish rate into squeeze holes 1 bpm at 1400 PSI.

Plug #4 with CR at 2029', mix and pump 52 sxs Class B cement (62 cf), squeeze 43 sxs outside casing below the CR and leave 9 sxs inside casing above the CR from 2029' up to 1913' to cover the Pictured Cliffs top.

PUH to 1907'. Reverse circulate the hole clean with 55 bbls 2% KCl water. Pressure test casing to 500 PSI, held OK for 5 minutes. TOH and LD all tubing and setting tool. Wait on test truck to test casing on chart. **Pressure test casing to 500 PSI on chart for 30 minutes.** ND BOP. NU wellhead. Remove Lockout / tagout. RD and MOL.

Henry Villanueva, Protocom representative, was on location. Troy Salyers, BLM representative, was on location.

