SEP 172008

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Empar ... remament

Sundry Notices and Reports on Wells	الموملية "أ	modern Florid Carlos
500-1, 1.0.000 and 1.0po. 0.000		
	5.	Lease Number NMSF-078135
Type of Well GAS	6.	If Indian, All. or Tribe Name
Name of Operator	7.	Unit Agreement Name Huerfanito Unit
BURLINGTON RESCURCES OIL & GAS COMPANY LP		
Address & Phone No. of Operator	8.	Well Name & Number Huerfanito Unit 90E
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No.
Location of Well, Footage, Sec., T, R, M		30-045-34399
Unit E (SWNW), 1910' FNL & 1170' FWL, Section 1, T26N, R09W, NMPM	10.	Field and Pool Basin Dakota
	11.	County and State San Juan Co., NM
Describe Proposed or Completed Operations 16/08 The subject well was drilled as Dakota standalone and completed on 5/12/09 0bwpd. Rig moved on and the lower Dakota perfs were found to have excessive vere plugged back without obtaining agency approval. Wayne Townsend (BLM) as	vater producti	on. The lower Dakota per
OI sundry was requested.		
K perf'd from 6332' – 6607' = 54 perfs BPs set @ 6465' & 6367', No Cement K perfs still open 6332', 6336', 6340', 6345', 6347', 6352', 6354'		RCVD SEP 19'08 OIL CONS. DIV. DIST. 3
BPs set @ 6465' & 6367', No Cement		OIL COMS. DIV.
BPs set @ 6465' & 6367', No Cement K perfs still open 6332', 6336', 6340', 6345', 6347', 6352', 6354'	atory Technicia	OIL CONS. DIV, DIST. 3