UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SEP 08 2008

DONEAU OF LAND MANAGEMENT		0 - .
Sundry Notices and Reports on Wells	Eur	er alle allana panonè Lampeta Alba Calle
1. Type of Well	5. 6.	Lease Number SF-080668 If Indian, All. or
GAS 2. Name of Operator	,7.	Tribe Name Unit Agreement Name
<u>Burlington</u>	•	
RESOURCES OIL & GAS COMPANY LP 3. Address & Phone No. of Operator	8.	San Juan 27-4 Unit Well Name & Number SJ 27-4 Unit #59N
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No.
4. Location of Well, Footage, Sec., T, R, M	10	30-039-30475
Unit B (NWNE), 175' FNL, 1706' FEL, Sec. 9, T27N, R4W, NMPM Surface Location Unit O (SWSE), 815' FSL & 2348' FEL, Sec. 4, T27N, R4W, NMPM Bottomhole	10.	Field and Pool Blanco MV/Basin DK/ Basin Mancos
	11.	County and State Rio Arriba Co., NM
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OT	HER I	DATA
Type of Submission X Notice of Intent Abandonment Recompletion Subsequent Report Plugging Casing Repair Final Abandonment Altering Casing Conversion to Injection Type of Action Change of Plans X Out New Construction New Construction Non-Routine Fracturing Water Shut off Conversion to Injection	ner – Sid	etrack RCVD SEP 30 '08 OIL CONS. DIV. DIST. 3
13. Describe Proposed or Completed Operations		
While drilling the subject well we encountered water at the Chacra interval and the able to drill to 5779', but ended up loosing 1 jt. drill pipe, 6 drill collars, a cross-ohole. The Top of Fish is @ 5569'. We fished for several days but were unable to set a cement retainer approx. 30' above the 7" shoe @ 4454' and then pump consection covering the fish with cement. We will then cut a window in the 7" casing sidetrack the well in a slightly easterly direction to avoid the fish and continue do (Jim Lovato) and OCD (Kelly Roberts) gave their approval on 9/6/08. See the at	over a recomment over the recomment of the recomment of the recomment over the recomment of the recomment over the recomment of the re	ond the air hammer down over fish. Plans now are to fill the open hole tabove the retainer and ble to TD. The BLM d sidetrack procedure.
14. I hereby certify that the foregoing is true and correct. Signed Patsy Clugston Title Regulatory Specialist	Da	ate <u>9/8/08</u> .
(This space for Federal or State Office use) APPROVED BY CONDITION OF APPROVAL, if any: Title 18 U S C. Section 1001, makes the crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or bounds at statements or representations as to any printing within assignment of the United States any false, fictitious or bounds at statements or representations as to any printing within assignment of the United States any false.	. n	Date 9/29/68

Burlington Resources

San Juan 27-4 Unit# 59N Well Name:

Type: Intermediate "S" curve

WAN.ZA2.7657

NESTOR SANCHEZ

Phones: 505-320-4133

Home: 505-326-5068

In case of Major Emergency Call 911

San Juan Business Unit - Drilling Program

Give the following information to Operator:

Well Name San Juan 27-4 Unit# 59N I atitude

36 59442N (NAD 1983)

County: Rio Arriba

36º 35.66463' N (NAD 1927) Longitude 1079 15.1339' W (NAD 1927) 107 25283W (NAD 1983) State: New Mexico

FROM BLANCO, TRAVEL EAST ON HWY 64 FOR 32 7 MILES TO MILE MARKER 106 MILES. FOLLOW THE RIG SIGNS TO THE RIGHT INTO A DIRT ROAD 'RIG TELEPHONE NUMBER 505

947-8954

Location:

Footage:

County:

Signed APD:

Rig:

GL:

KB:

Formation: Mesa Verde / Basin Dakota T - 27 N R-4W

185' FNL & 1706' FEL

AWS 184

02/25/08

7,167'

Rio Arriba State

New Mexico

API#: 30-039-30475

Sec 9

Lease#: USA SF-080668 BLM Phone #: 599-8907

DAYS: 23

7,181' 8,699

Office, 505-320-4013

MV/DK AFE#

MV/DK Network #. 10223556

SIDETRACK PROCEDURE

