

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCT 06 2008

FORM APPROVED
Budget Bureau No. 1004-0135
Expires March 31, 1993

SUNDY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir
Use "APPLICATION FOR PERMIT -" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Synergy Operating, LLC (163458) OGRID # 163458

3. Address and Telephone No

PO Box 5513 (505) 325-5549
Farmington, NM 87499

4. Location of Well (Footage, Sec, T, R, M, or Survey Description)

Unit L, 1470' FSL, 1125' FWL, Sec 05, T21N - R07W

Lease Designation and Serial No

NMNM-99735

6 If Indian, Allottee or Tribe Name

RCVD OCT 14 '08

7. If Unit or CA, Agreement Designation

OIL CONS. DIV.

8. Well Name and No

Synergy 21-7-5 # 133

9 API Well No

30-043-21038

10 Field and Pool, or Exploratory

Basin Fruitland Coal

11 County or Parish, State

Sandoval County
New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other
☒ Change of Plans
☒ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well
Completion or recompletion Report and Log Form)

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including, estimated date of starting work.

If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones of pertinent to this work

SYNERGY OPERATING, LLC completed the valid C-144 permit with the NMOC

SPUD Sundry

09-29-2008 Notified BLM of impending Spud, surface casing cement, and BOP testing.
MIRU Steve & Son Rig # 1 from Lindrith Yard. Spot Equipment. Spud 12-1/4" hole at 16:00 hrs on 09-29-2008
Drill ahead to 52'.

09-30-2008 Rig Repairs. Circulate and drill ahead to 85 feet.
Shut-down for repairs

Surface Casing and Cementing on next report ✓

ACCEPTED FOR RECORD

OCT 08 2008

FARMINGTON FIELD OFFICE
BY T. Salazar

14. I hereby certify that the foregoing is true and correct

Signed:

Thomas E. Mullins

Title: Engineering Manager

tom.mullins@synergyoperating.com

Date: 10-01-2008

Telephone (505) 599-4905

This space for federal or state office use

Approved by:

Conditions of approval if any

Title:

Date:

NMOC