


November 5, 2003

New Mexico Oil Conservation Division
1000 Rio Brazos Road
Aztec, New Mexico 87410



Jicarilla 67 #15
Unit G, Section 30, T 25 N, R 5 W
Rio Arriba Co., New Mexico
South Blanco Pictured Cliffs (72439) & Basin Dakota (71599)
Administrative Order R-11363, DHC 1073AZ
API # 30-039-21965

Dear Mr. Hayden:

Energen Resources recently finished a pay add and down hole commingling operations on the subject well. In accordance with the approved Administrative Order, the supervisor of the Aztec District Office of the NMOCD shall determine the proper production allocation.

Prior to commingling operations, the Dakota was producing at a stabilized rate of 90 MCFD & 0.25 BOPD. The Pictured Cliffs was added in March 2003 and the well was returned to production in March 2003. The well has stabilized at a rate of 130 MCFD & 0.25 BOPD. Decline curve analysis results in a Dakota producing rate of 87 MCFD in November 2003, had the Pictured Cliffs not been completed. The following allocation is recommended:

	<u>Gas</u>	<u>Oil</u>
Pictured Cliffs	33%	NA
Dakota	67%	100%

If additional information is needed, please contact me at 566-4680.

Sincerely Yours,

Charles J. Donahue
District Engineer