Form 3160-5 (August 2007)

Final Abandonment Notice

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

FORM APPROV	EĽ
OMB No. 1004-0	13′
Everes: July 31 3	201

5. Lease Serial No SF 079003

Water Disposal

6. If Indian, Allottee or Tribe Name

abandoned well.	Use Form 3160-3 (A	APD) for such proposa	ls.		
SUBM	IT IN TRIPLICATE – Othe	r instructions on page 2.	ED	7. If Unit of CA/Agree	ement, Name and/or No.
1. Type of Well		NOV 18 20		8. Well Name and No. 256H	
Name of Operator Devon Energy Production Company, L.P. Bureau of Land Management States and Manag		agement	9. API Well No 30-045-34685		
3a. Address P.O. Box 6459 Navajo Dam, NM 87419		3b. Phone Non(include area co	ide) C	10. Field and Pool or Exploratory Area S Los Pinos F/S Pictured Cliffs	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SL: 550' FNL & 2565' FEL, Unit B, NW NE, Sec. 34, 31N, 7W			11. Country or Parish, State San Juan, NM		
12. CHE	CK THE APPROPRIATE BO	OX(ES) TO INDICATE NATUR	E OF NOTIO	CE, REPORT OR OTHE	ER DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	=	luction (Start/Resume) amation	Water Shut-Off Well Integrity
Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon		omplete porarily Abandon	Other Completion Sundry

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Plug Back

On 10/11/2008 moved in Halliburton. Open Sliding Sleeve at MD 4971' and Fraced PC interval at MD 4774'-5184' with/500 gal 15% HCL Acid and 200,000# sand in cross/linked GEL. Open Frac Sleeve at MD 4575' and Fraced PC from MD 4375' to MD 4774' with 200,000# of sand in Cross/link GEL. Opened Sliding Sleeve at MD 4179' and Fraced PC interval MD 3979' to MD 4375' with 500 gal HCL Acid and 200,000# of 20/40 sand wedge in cross/link GEL.

On 10/24/2008 MIRUSU. Landed 2 3/8" J-55 tubing at 4152'. Released Rig on 10/30/2008. 🎝

Convert to Injection

RCVD NOV 25 '08

OIL COMS. DIV.

DIST. 3

	-	ACCEPTED FOR RECORD
	B	FARMINGTON FIELD OFFICE
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)	(Badana	
Katie Lam Title	Field Clerk	
Signature Date	11-18-08	
THIS SPACE FOR FEDERAL	OR STATE OFFICE USE	
Approved by		
	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person fictitious or fraudulent statements or representations as to any matter within its jurisdiction.	knowingly and willfully to make to any departi	ment or agency of the United States any false,
(Instructions on page 2)		