

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

RECEIVED

JUL 1 6 1993

RECEIVED

JUL 8 1993

OIL CON. DIV.

2. Name of Operator
MERIDIAN OIL

DIST. 3

Bureau of Land Management
Durango, Colorado

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1750' FSL, 940' FWL Sec. 15, T-32-N, R-14-W, NMPM

5. Lease Number
I-22-IND-2772

6. If Indian, All. or
Tribe Name
Ute Mt Ute

7. Unit Agreement Name

8. Well Name & Number
Ute #8

9. API Well No. ¹⁸
30-045-11410

10. Field and Pool
Paradox

11. County and State
San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☐ Notice of Intent

☐ Abandonment

☐ Change of Plans

☒ Subsequent Report

☐ Recompletion

☐ New Construction

☐ Final Abandonment

☐ Plugging Back

☐ Non-Routine Fracturing

☐ Casing Repair

☐ Water Shut off

☐ Altering Casing

☐ Conversion to Injection

☒ Other - sidetrack workover

13. Describe Proposed or Completed Operations

05-30-93 MOL&RU. Blow down. Pump 70 BW down tbgs. ND WH. NU BOP.

05-31-93 TOO H w/pkr. Ran scraper to 8140'. LD tbgs. Set CIBP @ 7840'. Ran seeker gyro log.

06-01-93 TIH w/section mill & HWDP. Would not cut. TOO H for new mill.

06-02-93 Section mill 7" csg 7658-7709'.

06-03-93 Mill 7709-18'. TOO H w/section mill. TIH w/under reamer. Open hole to 12" 7658-7712'. TOO H. TIH to 7840'. Spot 100 sx Class "G" cmt w/0.3% HR-5 and 0.3% CFR-3 and 0.5# Halad-413 (100 cu.ft.). Displace w/4 BW & 41 bbl mud. TOO H.

06-04-93 WOC. Dress off 7582-7668'. Circ & cond. TOO H. TIH w/BHA.

06-05-93 Time drl off cmt plug 7668-7704'. Drl to 7765'.

06-06-93 Drl to 7984'.

06-07-93 Slide drl to 8093'. Change out BHA. Ream 7998-8040'. Work stuck pipe @ 8040'.

06-08-93 Ream 8026-93'. Drl to 8254'.

06-09-93 Drl 8254-8337'.

06-10-93 Drl to 8510'. Circ & cond.

(cont'd on back)

14. I hereby certify that the foregoing is true and correct.

Signed Jerry S. Hubbard Title Regulatory Affairs Date 7/7/93

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

OPERATOR'S COPY

06-11-93 Drl to 8735' MD.
06-12-93 Drl to 9040' MD.
06-13-93 Drl to 9180' MD.
06-14-93 Drl to 9380' MD.
06-15-93 Drl to 9480' MD.
06-16-93 Drl to 9549' MD.
06-17-93 Drl to 9685' MD.
06-18-93 Drl to 9803' MD.
06-19-93 Drl to 9960' MD.
06-20-93 Drl to 10102' MD.
06-21-93 Drl to 10273' MD.
06-22-93 Drl to 10413' MD.
06-23-93 Drl to 10585' MD.
06-24-93 Drl to 10751' MD.
06-25-93 TOOH LD BHA.
06-26-93 TIH w/coil tbg to 10722'. Displace hole w/ KCl wtr. TOOH to 6000'. Unload w/N2.
06-27-93 TIH to 7100', hit bridge. TOOH w/coil tbg, lost electric line & hydrojet wash head. Fishing.
06-28-93 Found hole in coil tbg @ 2240', cut off & LD btm 2240'. LD 2000' wireline. TIH w/spear, lost spear.
06-29-93 TIH w/overshot, tag @ 7908'. Work over fish to 7950', TOOH, no fish. TIH, wash 7950-97', stuck @ 7977'. TOOH, left shoe in hole.
06-30-93 TIH w/bit, circ & cond @ 7959'. TOOH. TIH w/mill.
07-01-93 TIH, tag @ 7710'. Ream 7710-7759'. Chase fish down hole 7959-7992'. Work stuck pipe @ 7965'.
07-02-93 Fishing.
07-03-93 Tag fish @ 7932'. Jar on fish. TOOH w/part of fish.
07-04-93 TIH to 7955'. Work spear @ 7955'. TOOH, spear bent, no fish. Ream 7718-7992'. Stuck pipe @ 7965'.
07-05-93 Shot 8 holes @ top of mill @ 7963'. Try to circ. Try to back off @ 7959'. Reran string shot, backed off @ 7953'. TOOH. Left pilot mill, x-over sub, bumper sub (12.27'). Top of fish @ 7953'. TOOH
07-06-93 TIH to top of fish. Spot 56 sx Class "B" cmt w/0.03% CFR-3, 0.05% Halad 413, and 0.03% HR-5 (56 cu.ft.). Displace w/4 BW, and 47 bbl mud. TOOH w/DP. ND BOP. Notified D. Ravonwitz w/BLM of change of plans @ 9:30 am. 7-6-93.
07-07-93 Released rig. Will move back on in approximately 30 days.