Form 3160-5

.0/25/

-0/26/

UNITED STATES

FORM APPROVED

(August I	999)	DEPARTMENT OF TH BUREAU OF LAND MA		RECE	VED)	OMB No. 1004-0135 Expires November 30, 2000	
	SUND	DV NOTICES AND BE	DORTS ON WE	LLS	ľ	sse Serial No. SF078480	
	Do not use t abandoned v	this form for proposals well. Use Form 3160-3 (A	to drill or to re- NPD) for such pro	enter an Deposals.	M 11: 26 III	ndian, Allottee or Tribe Name	
	SUBMIT IN T	RIPLICATE - Other ins	tructions on re	verse side	ion. N <i>a</i> - iru	Juit or CA/Agreement, Name and/or N	
I. Type	of Well						
	il WellXXX Gas Well	8. We	Il Name and No.				
2. Name	e of Operator		DERAL E #1R				
	IX HYDROCARBON	9. API	Well No.				
3a. Addre		3b. Phone No. (include area code)			10 5:-1	30-045-31816	
	OX 3638, MIDLA	ND, TEXAS 79702 432-686-9869 , T., R., M., or Survey Description)				10. Field and Pool, or Exploratory Area BLANCO MESAVERDE	
		L; L; SEC 25; T-				nty or Parish, State	
	SO of BLANCO	1	N JUAN CO, NEW MEXICO				
20 1111	50 01 BLANCO				J. JAN	V JUAN CO, NEW MEXICO	
	12. CHECK AI	PPROPRIATE BOX(ES)	TO INDICATE N	ATURE OF NO	TICE, REPORT,	OR OTHER DATA	
ТҮРЕ	OF SUBMISSION	TYPE OF ACTION					
.		Acidize	Deepen	Produc	ction (Start/Resume)	Water Shut-Off	
U Noti	ice of Intent	Alter Casing	Fracture Trea	t 🔲 Reclan	nation	Well Integrity	
⊠ K Subs	sequent Report	Casing Repair	New Construc	ction 🔲 Recom	plete	XX Other SPUD & DRLG	
		Change Plans	Plug and Aba	ndon 🛄 Tempo	rarily Abandon		
☐ Fina	I Abandonment Notice	Convert to Injection	Plug Back	Water	Disposal		
Attach follow testing	the Bond under which the investment of the inves	he work will be performed or provided operations. If the operations and Abandonment Notices shall	rovide the Bond No. on results in a multip	on file with BLM/BL le completion or reco	 A. Required subsequences In a new interpretain 	lepths of all pertinent markers and zon tent reports shall be filed within 30 di terval, a Form 3160-4 shall be filed or we been completed, and the operator i	
/24/03	RU Bearcat	#5; Spud @ 2:15	AM.				
25/03	cmt, w/add pressure c	itives-2% CC, $1/4$	# Flocele @	15.6# ppg;	cir 10 bbl	on-cmt w/175 sks std s cmt to surface; hr test BOP to 1500	
26/03	2,150'; dr	·1g					
		Continue o	on back				
14. I hereb	y certify that the foregoin	ng is true and correct					
Name	<i>(Printed/Typed)</i> 11is R. Gunte		Tit	ie Agent			
Signati	ure PAIII	lis A Gun	to Da	ate 11/11/	03		
		THIS SPACE	FOR FEDERAL (OR STATE OFFIC	CE USE	CCEPTED FOR DECOR	
						TEUTE	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department seggency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Title

Office

Date

NOV 2 5 2003

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

10/27/03 3,687'; drlg. 4,158'; drlg. 10/28/03 10/29/03 4,740' drlg; RU Schlumberger to log. Ran Density-Neutron & Induction logs; run 114 jts 4½", 10.5#, J-55 csg, 10/30/03 set @ TD 4,746'; RU Halliburton & cmt w/50 sks std & 240 sks 50/50/std/POZ cmt @ 13.32# gal, w/6% Halad 9, 5# Gilsonite & 1/4# Flocele; circ 5 bbls good cmt to surf; press up csg to 1200 psi, held OK for 26 min. Hookup Halliburton; pump 2nd stage, lead cmt 570 sks std @ 13.3 ppg 10/31/03 w/2% econolite, .2% Veraset, .8% Halad 9, 5# Gilsonite & 1/4# Flocele; tail, 100 sks std w/5# 15.4 pp Gilsonite & 1/4# Flocele; PD @ 8:02 AM: circ out 5 bbls cmt out on 1st stage & 55 bbls CMT on 2nd stage; cut off & set slips @ 10:00AM; RD. 11/6/03 MIRU Triple P Well Service; NU BOP; PU 3%" mill & 6-31%" DC; PU 95 its 23%" tbg & RIH, tag cmt @ 3,245'; drlg 136' cmt to DV tool @ 3,381'; RD swivel; RIH & tag soft cmt @ 4,632'; drlg to float collar @ 4,702'. 11/7/03 Tag btm, no fill, displace hole w/4% KCL; press test csg to 500#, OK; POH LD 2%" tbg & 6-DC; ND BOP; RU Computa Log & run cmt Bond

Log; RD wireline; RD rig & equip; PBTD 4,696'.