UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED OMB NO. 1004-0137 Expires July 31, 2010

6. If Indian, Allottee or Tribe Name

5 Lease Serial No.

NMSF 077951 A

5 Lease Seriai No.

_					MAR	റ	5	2000
SUNDRY	NOTICES	AND	REPORTS	ON	WELLSMAR	Æ,	U	2003

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals in Field Office.

abandoned wen. Ose For	III 3100-3 (APD) 10	r such Hamington Fiel	d Office			
SUBMIT IN TRIPLICA	7.	7. If Unit or CA/Agreement, Name and/or No				
1. Type of Well Oil Well X Gas Well Other 2. Name of Operator		8. Well Name and No. Frost #2				
Energen Resources Corporation			9.	API Well No.		
3a. Address		3b. Phone No. (include are		30-045-02619		
2010 Afton Place, Farmington, NM 8		(505) 325-6800		10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey	Description)		Fu	lcher Kutz Pictured		
1,150' FSL & 850' FEL, Sec: 27, T:2	:: P	<u>C1</u>	iffs			
	11	11. County or Parish, State				
	Sa	n Juan NM				
12. CHECK APPROPRIAT	E BOX(ES) TO IN	DICATE NATURE OF N	OTICE, REPORT,	OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION					
x Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (Star	rt/Resume) Water Shut-Off Well Integrity		
Subsequent Report	Casing Repair	New Construction	Recomplete	Other		
		\equiv	<u> </u>			
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Ab			
RF .	Convert to Inject	ion Plug Back	Water Disposal			
1. MIRUPU. NDWH. NU BOP. 2. POOH w/ 1 1/4" IJ J-55 tbg. 3. RUWL. RIH w/ 3 1/2" CIBP & se 4. TIH w/ 1 1/4" IJ tbg. Mix & p 5. RUWL. RIH & perforate 3 squee 6. RBIH w/ 3 1/2" cmt retainer @ 7. TIH w/ 1 1/4" IJ tbg. Mix & p 8. RUWL. RIH & perforate 3 squee 9. Mix & Pump 40 sxs of Class B 10. ND BOP. Cut off WH. Install I 11. RDMOPU. Clean Location.	oump 78 sxs of 0 eze holes @ 1,49 @ 1,440'. POOH. oump 89 sxs of 0 eze holes throug omt down 3 1/2"	Hass B cmt (50% exc 90'. POOH. RDWL. Hass B cmt (50% exc ph 3 1/2" & 5 1/2" c	ess). POOH. ^{(?} asings (! 171'.	spot Ojs Alamo @ 1262'		
14. I hereby certify that the foregoing is true and correct Name (Printed Typed) Andrew Socio		Title Distric	et Engineer	ridi. e		
Signature	2	Date 3/25/09	10E 110E			
		DERAL OR STATE OFF	ICE USE	Date MAR 3 0 2009		
Approved by Original Signed: Stephen I	Mason	A RICE		MAK J U ZOUS		
Conditions of approval, if any, are attached. Approval of this not the applicant holds legal or equitable title to those rights in the su		tify that Office				

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: 1 Federal

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made:
- a) Place the Pictured Cliffs/Fruitland plug from 2256' 1899'.
- b) Place the Kirtland/Ojo Alamo plug from 1490' 1212' inside the 3 $\frac{1}{2}$ " casing and outside the 5 $\frac{1}{2}$ " casing.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.