

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

APR 21 2009

FORM APPROVED
Budget Bureau No 1004-0135
Expires March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir
Use "APPLICATION FOR PERMIT -" for such proposals

Bureau of Land Management
Farmington Field Office

SF-079033

5 Lease Designation and Serial No

6 If Indian, Allottee or Tribe Name

RCVD MAY 8 '09

7 If Unit or CA, Agreement Designation

OIL CONS. DIV.

8 Well Name and No

DIST. 3

San Juan 29-5 Unit Com # 92

9 API Well No

30-039-30395

10. Field and Pool, or Exploratory

Blanco Mesaverde

11 County or Parish, State

Rio Arriba County, NM

SUBMIT IN TRIPLICATE

1 Type of Well

☐

Oil Well

☒

Gas Well

☐

Other

2 Name of Operator

OGRID (163458)

Synergy Operating, LLC (designated agent for ConocoPhillips this well)

3 Address and Telephone No

P.O. Box 5513, Farmington, NM 87499

(505) 325-5449

4 Location of Well (Footage, Sec, T R, M, or Survey Description)

Unit G, 1655' FNL, 1405' FEL, Sec 23, T29N - R05W

320 acres (E/2) - 280 Acres are within the 29-5 Unit boundary

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒

Notice of Intent

☐

Subsequent Report

☐

Final Abandonment Notice

☐

Abandonment

☐

Recompletion

☐

Plugging Back

☐

Casing Repair

☐

Altering Casing

☒

Other: Timing Limitation

☐

Change of Plans

☒

New Construction

☐

Non-Routine Fracturing

☐

Water Shut-Off

☐

Conversion to Injection

☐

Dispose Water

(Note Report results of multiple completion on Well
Completion or recompletion Report and Log Form)

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including, estimated date of starting work

If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones of pertinent to this work

SYNERGY OPERATING, LLC IS THE DESIGNATED AGENT TO DRILL AND COMPLETE THE SUBJECT WELL WITHIN THE SAN JUAN 29-5 UNIT BOUNDARY. SYNERGY HOLDS MAJORITY OWNERSHIP IN THIS SPACING UNIT.

SYNERGY HAS BEEN REPEATEDLY DELAYED IN OUR DEVELOPMENT PROGRESS ON THE SUBJECT WELL OBTAINING THE NECESSARY PERMITS FOR ARCHAEOLOGICAL EXCAVATION.

SYNERGY IS REQUESTING AN EXEMPTION FROM THE REQUIREMENTS OF THE LAGUNA SECA WILDLIFE (SDA) TIMING LIMITATION TO COMMENCE WITH THE ARCHAEOLOGICAL SITE EXCAVATION ACTIVITY BY OUR CONTRACTOR - DIVISION OF CONSERVATION ARCHAEOLOGY.

SYNERGY HAS AN APPROVED ARPA PERMIT FOR THE EXCAVATION OF THE SUSPECTED SITE. THIS WELL LOCATION IS LOCATED IMMEDIATELY ADJACENT TO US HIGHWAY 64. IN ADDITION, ROAD CONSTRUCTION ACTIVITY HAS COMMENCED ON THE NEARBY LA JARA BRIDGE SEGMENT

SYNERGY DOES NOT BELIEVE THAT THE ARCHAEOLOGICAL INVESTIGATION ACTIVITY WOULD CONSTITUTE A SIGNIFICANT DISTURBANCE TO THE WILDLIFE. SYNERGY RESPECTFULLY REQUESTS AN EXEMPTION TO PERFORM THIS LIMITED TYPE OF WORK PRIOR TO THE LIFTING OF THE TIMING LIMITATION (TL) ON JUNE 15, 2009.

14. I hereby certify that the foregoing is true and correct

Signed:

Thomas. E. Mullins

Title

Engineering Manager

Date

04-20-2009

tom.mullins@synergyoperating.com

This space for federal or state office use

Approved by:

Title

Petr. Eng.

Date:


5/7/09


Conditions of approval if any

See attached Corts

Title 18 U.S.C. Section 1001, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious, or fraudulent statements or representations as to any matter within its jurisdiction

NMOCD





**San Juan 29-5 Unit Com #92
Unit G, 1655' FNL and 1405' FEL
Sec 23-29N-5W
Lease No. SF-079033**

Note: The proposed well is actually located in the Rosa SDA which carries a seasonal timing restriction of 12/01 – 03/31. No exception is necessary at this time.

However, if project delays require construction activities to be conducted during the above seasonal restrictions, a formal exception request must be filed with this office.